Date Filed: October 06, 2026

Witness: Christopher E. Colorio, Mark P. Baldwin, John G. Griffin and Leanne M. Landry
Request from: Office of Education, Outreach, and Enforcement

Question:

(MS24F-VENDOR-CIVIL) Refer to Exhibit ACCT-2 CLP-6, and Confidential Exhibit ACCT-2 CLP-6A-6, pp. 228-229. The Company reported an incremental charge of $5,968 for the Henkels & McCoy vendor. The charge related to repairs resulting from "truck ruts" resulting from Eversource Storm Work that appears to be at a residential address (p. 229). Explain how Eversource vehicles could have incurred damage to the referenced property requiring the $5,968 of repairs (i.e., over 1600 square feet of loam/seed). Furthermore, explain why the Eversource vehicles needed to drive on the property and identify the proximity of the damage to the public road.

Response:

During this event a tree came down, broke a secondary pole located in the middle of a customer's front yard and ripped the service off the house as well as the customer's meter. The pole is approximately 100' from the road and 50' from the driveway and cannot be reached from either drivable surface. Their driveway is also a very narrow unpaved driveway made for private vehicles and not for large bucket trucks. Repairs had to be made to the grass along the sides of the driveway as well as around the pole since the vehicles were too large to stay within the drivable surfaces and needed offroad access to the pole. The event number related to this outage is 5306544.