work_order_number	description	long_description	cost_element_group	ferc_account	percent
1B321594	TB- 772 MONROE TPKE POLE 268 INSTAL	TB- 772 MONROE TPKE POLE 268 INSTALL CV SERVICE	Contributions-C01	107010	1
1B620199	15 BATES PL Elec Svc New Residenti	15 BATES PL Elec Svc New Residential PR2/4/16	Contributions-C01	107010	1
1B621534	ROX, 142 EAST FLAG SWAMP, TEL REPL	ROX, 142 EAST FLAG SWAMP, TEL REPL POLE. HANG POT AND OH/DB SVC FOR GATE AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1B621706	BM/ INS 3P PRI RISER, RUN 390' 1AL	BM/ INS 3P PRI RISER, RUN 390' 1AL 4CT TO NEW 500KVA PAD AP2-YWO Total Cost Variance Met - Variance :24.7788 MIN.:-50 MAX.:50	Contributions-C01	107010	1
1B720975	116 N LAKE SHORE DR Elec Svc New R	116 N LAKE SHORE DR Elec Svc New Residential AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1G520647	RL:48 Clapboard Ridge Rd; Elec Svc	RL:48 Clapboard Ridge Rd; Elec Svc Existing Residential IT Meter 600 Amps (DN) AP2-YWO Total Cost Variance Met - Variance :109.6871 MIN.:-50 MAX.:150	Contributions-C01	107010	1
1G620491	RL:35 Mooreland Rd; Elec Svc New Re	RL:35 Mooreland Rd; Elec Svc New Residential IT 600 amp Meter DESG NO AWOCS-AWOCS REASON CODE AND DESCRIPTION NOT FOUND.	Contributions-C01	107010	1
1G620693	Elec Svc New Com/Ind IT Meter DESG	Elec Svc New Com/Ind IT Meter DESG (DN) AP2-YWO Total Cost Variance Met - Variance :-18.0765 MIN.:-40 MAX.:40	Contributions-C01	107010	1
1N522299	KS 645 POST RD E, WSPT P# 18505 INS	KS 645 POST RD E, WSPT P# 18505 INS PRI RISER, DB PRI, PRI VLT, & 300KVA PAD AP2-YWO Total Cost Variance Met - Variance :19.9624 MIN.:-50 MAX.:50	Contributions-C01	107010	1
1N522364	AJC 183 HEMLOCK HILL RD NC UPGRD TR	AJC 183 HEMLOCK HILL RD NC UPGRD TRANS & INST RISER FOR 320A SC SERV POLE 5713	Contributions-C01	107010	1
1N621035	KS 9 COLONIAL RD, WSPT P# 781 INS C	KS 9 COLONIAL RD, WSPT P# 781 INS CROSSOVER POLE & 200A OH/DB SVC AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1S520664	PH; 48 SALISBURY RD; Electric Servi	PH; 48 SALISBURY RD; Electric Service New Residential SC w/CIAC Line Set	Contributions-C01	107010	1
1S720520	DL; 2 SELLECK ST; NEW 3PH PRIMARY R	DL; 2 SELLECK ST; NEW 3PH PRIMARY RISER TO NEW PAD XFMR - BLT NL-YWO Variance - NU Construction Labor	Contributions-C01	107010	1
2C520200	Salisbury, 128 Rocky Ln -- ins pri	Salisbury, 128 Rocky Ln -- ins pri ple line then db to pedestal	Contributions-C01	107010	1
2L320454	Colebrook--Rockwell Rd. (81) 7510	Colebrook--Rockwell Rd. (81) 7510 Repl x-fmr, run span secd APPT: AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
2L520353	BETHLEHEM,76 & 78 CRANE HOLLOW RD//	BETHLEHEM,76 & 78 CRANE HOLLOW RD//EXISTING SVC CHANGES & UPGRADES// OH TO DB AP2-YWO Total Cost Variance Met - Variance :35.2001 MIN.:-50 MAX.:50	Contributions-C01	107010	1
2L620302	cornwall, dibble hill rmv oh R.O.	cornwall, dibble hill rmv oh R.O.W ins db up driveway to upgraded svc AP2-YWO Total Cost Variance Met - Variance :23.2749 MIN.:-50 MAX.:50	Contributions-C01	107010	1
2L620485	WARREN,39 BLISS RD//REMOVE POLE LIN	WARREN,39 BLISS RD//REMOVE POLE LINE & INSTALL DB PRIMARY, PAD &SWITCH// AP2-YWO Total Cost Variance Met - Variance :-3.7348 MIN.:-50 MAX.:50	Contributions-C01	107010	1
2L620873	LITCHFIELD,12 NORFOLK RD// INSTALL	LITCHFIELD,12 NORFOLK RD// INSTALL NEW 300 KVA DB XFMRFOR NEW MUSIC CENTER// AP3-YWO Resource Variance Met- Labor 11 <= 32 OR 27.01 <= 30 And Contractor $0 <= 2000	Contributions-C01	107010	1
2L720416	Canton--Collins Rd. (15) 2274 inst	Canton--Collins Rd. (15) 2274 inst 25kva xfmr, inst xover pole, secd riser & svc AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
2M520173	Jpt-Steeplechase Dr SOG - Lighting	Jpt-Steeplechase Dr SOG - Lighting - Muni - Public Roadway - COMP 8-4 CCC AP2-YWO Total Cost Variance Met - Variance :38.665 MIN.:-50 MAX.:50	Contributions-C01	107010	1
2M620326	WC/JJH-49 Depaolo Dr, Southington.	WC/JJH-49 Depaolo Dr, Southington. CO-GEN INTERCONNECT CI-YWO Variance - Contractor Invoice	Contributions-C01	107010	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
2M622490	AMM 172 SCOTT SWAMP RD,FARMINGTON.	AMM 172 SCOTT SWAMP RD,FARMINGTON. INSTALL NEW OH SERVICE. AP2-YWO Total Cost Variance Met - Variance :-6.9374 MIN.:-50 MAX.:50	Contributions-C01	107010	1
2M623119	EJC 489 Columbus Blvd, NB Install P	EJC 489 Columbus Blvd, NB Install P#9576 1ph Riser, Pad, Svc to Bldg, M/L/C AP2-YWO Total Cost Variance Met - Variance :5.2071 MIN.:-50 MAX.:50	Contributions-C01	107010	1
2M721190	DM 811 Queen St SOG ALDI's INST 3PH	DM 811 Queen St SOG ALDI's INST 3PH Primary & 300KVA XFMR 1000 AMP 120/208 SVC AP2-YWO Total Cost Variance Met - Variance :-6.1671 MIN.:-50 MAX.:50	Contributions-C01	107010	1
2M721206	AMM 788 FARMINGTON AVE,FARMINGTON.	AMM 788 FARMINGTON AVE,FARMINGTON. INSTALL NEW 3PH DB SERVICE. AP3-YWO Resource Variance Met- Labor 4 <= 32 OR 8.38 <= 30 And Contractor $0 <= 2000	Contributions-C01	107010	1
2M721712	WC-420 N Main ST,Sog. Upgrade svc t	WC-420 N Main ST,Sog. Upgrade svc to 3ph 480/277. M/L coordinate AP2-YWO Total Cost Variance Met - Variance :43.8246 MIN.:-50 MAX.:50	Contributions-C01	107010	1
3H621725	RF-1150 Elm St Ext.,RHl,Install 3PH	RF-1150 Elm St Ext.,RHl,Install 3PH XFMR Bank on pole4966 & install OH/UG SVC AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
3H720935	RF-970 Marshall Phelps Rd,Windsor,	RF-970 Marshall Phelps Rd,Windsor, Install new OH/UG Sec SVC AP2-YWO Total Cost Variance Met - Variance :-5.3741 MIN.:-50 MAX.:50	Contributions-C01	107010	1
3S520060	Elec Svc Existing Com/Ind DESG (DN)	Elec Svc Existing Com/Ind DESG (DN)	Contributions-C01	107010	1
4D720188	Bahr Rd, #3 Deep River/TL-INST (65'	Bahr Rd, #3 Deep River/TL-INST (65',4/03CT) OH-DB SVC FROM P#423 ON W ELM ST AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
4D720605	TS 7 FERRY LA 40778 EC RMV OH SVC I	TS 7 FERRY LA 40778 EC RMV OH SVC INSTALL OH/DB SVC NOT SURE IF APPOINT REQUIRED AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
4E420733	74 MIDDLE HADDAM RD E HMPTN AT NEW	74 MIDDLE HADDAM RD E HMPTN AT NEW P-40 INST PRI RISER, PAD XF, SVC AP3-YWO Resource Variance Met- Labor 12 <= 32 OR 29.54 <= 30 And Contractor $1020.59 <= 2000	Contributions-C01	107010	1
4N620766	GCC / REMOVE AND RELOCATE FACILITIE	GCC / REMOVE AND RELOCATE FACILITIES / STREET LITES	Contributions-C01	107010	1
4N620866	SM-1 LAMBERTS LN, STGN- EVRSRC RPLC	SM-1 LAMBERTS LN, STGN- EVRSRC RPLC 2 POLES INSTALL OH-DB SVC- APPNT REQ AP2-YWO Total Cost Variance Met - Variance :-6.923 MIN.:-50 MAX.:50	Contributions-C01	107010	1
4N621635	GCC / FRONTIER I&R POLE / SHIFT FAC	GCC / FRONTIER I&R POLE / SHIFT FACILITES/INSTALL NEW SVC RISER TO DB SVC TO HOM AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
4N720247	SM-265 NW CRNR RD, N STGN- FRNT RPL	SM-265 NW CRNR RD, N STGN- FRNT RPLC PLE, OH XFMR, OH-DB SVC AP3-YWO Resource Variance Met- Labor 26 <= 32 OR 166.67 <= 30 And Contractor $571.4 <= 2000	Contributions-C01	107010	1
5D221491	DG P#2411 RPLC 1 SECT NEUTRAL W/TPX	DG P#2411 RPLC 1 SECT NEUTRAL W/TPX, 1 SECT TPX XROAD, OH/DB SVC RSR	Contributions-C01	107010	1
5T621973	80 Hayes Rd, SW / 2775 / INS NEW CV	80 Hayes Rd, SW / 2775 / INS NEW CV SVC	Contributions-C01	107010	1
1N720793	RM 139 Lords Hwy Weston Install pr	RM 139 Lords Hwy Weston Install primary riser to new pad and db svc AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
2M721032	(DF) drhm(I) 277/480 Padmount XF &	(DF) drhm(I) 277/480 Padmount XF & 400A DB svc -- New Com/Ind DESG (DN) AP2-YWO Total Cost Variance Met - Variance :1.0538 MIN.:-50 MAX.:50	Contributions-C01	107010	1
3H720896	NJB WEST ST R.H. RPL CUTOUT & RISER	NJB WEST ST R.H. RPL CUTOUT & RISER ON P#1481 CUST OUTAGE ON 6/2/17? @ 5PM AP2-YWO Total Cost Variance Met - Variance :4.7256 MIN.:-50 MAX.:50	Contributions-C01	107010	1
1S720604	BK 1011 WASHINGTON BLVD INSTALL 3RD	BK 1011 WASHINGTON BLVD INSTALL 3RD TRANSFORMER IN LOOP 300KVA AP2-YWO Total Cost Variance Met - Variance :37.0399 MIN.:-40 MAX.:40	Contributions-C01	107010	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
4D720645	Cottage Rd, #11 Old Saybrook/TL-INS	Cottage Rd, #11 Old Saybrook/TL-INST 4/03CT OH-DB SVC [WORKS W/ WR#2914467] AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1S620993	PH; 151 BROOKSIDE RD; INSTALL 200AM	PH; 151 BROOKSIDE RD; INSTALL 200AMP DB, REMOVE 100AMP DB SERVICE AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
4N720645	SM-2 WASHINGTON ST, STGN- INSTL 250	SM-2 WASHINGTON ST, STGN- INSTL 250 KVA 1 PH XFMR/ IT METER AP2-YWO Total Cost Variance Met - Variance :112.9059 MIN.:-50 MAX.:150	Contributions-C01	107010	1
1S720716	DM/356 DAVIS AVE GREENWICH: INST 3"	DM/356 DAVIS AVE GREENWICH: INST 3" SVC RISER, 350MCM DB SVC, 2-200AMP METERS AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
4E621233	JK>PAD 533--EXTEND DB SEC TO (3) NE	JK>PAD 533--EXTEND DB SEC TO (3) NEW HH'S FOR CONDO UNITS NL-YWO Variance - NU Construction Labor	Contributions-C01	107010	1
3H721758	WF-109 Pond Rd-Windsor-@ pole-1853,	WF-109 Pond Rd-Windsor-@ pole-1853,inst new oh/db svc to hse AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1S720478	DM/8 PARK AVE GREENWICH: INTERCEPT	DM/8 PARK AVE GREENWICH: INTERCEPT EXIST DB SVC, 4/0 DB SVC, 200AMP AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
4N721202	SM-122 RYDER RD, N STGN-Install new	SM-122 RYDER RD, N STGN-Install new 150' OH/DB service AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1S720506	DL; 970 STILLWATER RD; TRANSFER TO	DL; 970 STILLWATER RD; TRANSFER TO FRONTIER POLE 113347/NEW OH/DB RISER AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1S720372	DL; 16 EMERY DR E; REPLACE BACKYARD	DL; 16 EMERY DR E; REPLACE BACKYARD POLE AND INSTALL NEW OH/DB SVC RISER AP2-YWO Total Cost Variance Met - Variance :53.9906 MIN.:-50 MAX.:150	Contributions-C01	107010	1
1S720997	PH; 165 BOUTON ST W; INSTALL NEW 20	PH; 165 BOUTON ST W; INSTALL NEW 200AMP DB; REPLACE POLE 925 AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
5T721787	Hall HillRd.,23,Somers,install 4/0q	Hall HillRd.,23,Somers,install 4/0qpxsec,(2) risers 200,400amp 3phase 120/208 AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
2C720130	replace and relocate svc from oh to	replace and relocate svc from oh to db pole 406 upper main st sharon appt needed AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
5T720934	Winderemere Ave 160, Ellington. OH/	Winderemere Ave 160, Ellington. OH/DB svc 4/0 375 ft from XFR-P-33646. Mtr dept AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1S720173	PH; 16 RAIDERS LN; INSTALL 400AMP D	PH; 16 RAIDERS LN; INSTALL 400AMP DB SERVICE, REMOVE OH POLE LINE/SERVICE AP2-YWO Total Cost Variance Met - Variance :56.1339 MIN.:-50 MAX.:150	Contributions-C01	107010	1
4N720929	MM SERVC RISER TO PEDESTALL POLE214	MM SERVC RISER TO PEDESTALL POLE214 PEQOUT AVE OH/DB MLC AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1B721402	TB- 29 WEST ST INSTALL NEW X OVER P	TB- 29 WEST ST INSTALL NEW X OVER POLE AND DB SERVICE AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1N721098	JES; 66 WHITE FALL LN NEW CANAAN.;	JES; 66 WHITE FALL LN NEW CANAAN.; Elec Svc Existing Residential POLE 8525... AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
4D721154	CB//Madison, 74 Wall St//New db ped	CB//Madison, 74 Wall St//New db pedestal svc for town lights AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1N720608	JDB 18 FLICKER LN NWLK SHIFT POLE 6	JDB 18 FLICKER LN NWLK SHIFT POLE 6545 INSTALL New OH/DB Residential DESG (DN) AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
4N721203	SM-240 BOSTON POST RD, WTRFRD- RMV	SM-240 BOSTON POST RD, WTRFRD- RMV OH SVC AND INSTL OH-DB AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
5T721759	Hall Hill Rd.353,Somers, install 25	Hall Hill Rd.353,Somers, install 25KVA 120' 1/0tpx new40/2 4/0db service AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
4N621483	SM-249 PALMER NECK RD, STGN- RPLC P	SM-249 PALMER NECK RD, STGN- RPLC POLE/, INSTL XFMR/INSTL OH-DB SVC AP2-YWO Total Cost Variance Met - Variance :82.3711 MIN.:-50 MAX.:150	Contributions-C01	107010	1
4D720194	CB//MADISON, 57 MIDDLE BEACH RD W//	CB//MADISON, 57 MIDDLE BEACH RD W//NEW SVC, SHIFT POLE/WORKS W TEMP RMVL AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
1S811292	RL;159 Breezy Hill Rd; Elec Svc Exi	RL;159 Breezy Hill Rd; Elec Svc Existing Residential DESG (DN) AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
2L720676	KENT,45 KENT CORNWALL RD//RUN NEW O	KENT,45 KENT CORNWALL RD//RUN NEW OH/DB SVC TO BARN FROMP#15464 ON GREENWOOD LN AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
3H721859	42 Grassmere Ave., W. Htfd - Instal	42 Grassmere Ave., W. Htfd - Install new OH/DB svc (single-phase, 120/208) AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1N621689	JDB 18 OX YOKE LN NWLK P9366 EXTEND	JDB 18 OX YOKE LN NWLK P9366 EXTEND PRI INS 50KVA & OH/DB SVC DESG (DN) AP2-YWO Total Cost Variance Met - Variance :-19.5236 MIN.:-40 MAX.:40	Contributions-C01	107010	1
4N720196	GCC / EVERS/INSTALL NEW POLE/PRI RI	GCC / EVERS/INSTALL NEW POLE/PRI RISER TO PAD MTD XFMR NL-YWO Variance - NU Construction Labor	Contributions-C01	107010	1
1S721655	DM/7 INDIAN HEAD RD RIVERSIDE: INST	DM/7 INDIAN HEAD RD RIVERSIDE: INST 3" SVC RISER, 350MCM DB SVC, 400AMP AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
2C720133	ins new db svc to beckley furnace l	ins new db svc to beckley furnace lower rd north canaan AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1B722524	TB 154 ENTERPRISE DR INSTALL NEW PR	TB 154 ENTERPRISE DR INSTALL NEW PRIMARY SVC AND 300 KVA XFMR AP2-YWO Total Cost Variance Met - Variance :49.4991 MIN.:-50 MAX.:50	Contributions-C01	107010	1
4E720474	(CH) P#2427: RPL EXIST'G OH/DB SVC	(CH) P#2427: RPL EXIST'G OH/DB SVC WITH NEW 4/0 OH/DB SVC_85' AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1S720461	RL:11 Watch Hill Dr:Elec Existing R	RL:11 Watch Hill Dr:Elec Existing Residential OH/DB Remove span Tpx & OH service AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1N721672	AJC 54 WILTON RD WSPT REPLACE POLE	AJC 54 WILTON RD WSPT REPLACE POLE 1205 INSTALL P RISER & PAD REM P DB PRI & DH	Contributions-C01	107010	1
1N522133	AJC 128 MATHER ST WLTN INSTALL RISE	AJC 128 MATHER ST WLTN INSTALL RISER FOR 480V 3PH DELTA SERVICE P24555 AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
4D720314	S Cove Rd II, #34 Old Saybrook/TL-I	S Cove Rd II, #34 Old Saybrook/TL-INST 4/03CT OH-DB SVC@P#576 *FLOOD PLAIN INST*	Contributions-C01	107010	1
4N621319	Elec Svc New Com/Ind DESG (DN)	Elec Svc New Com/Ind DESG (DN)	Contributions-C01	107010	1
1B721060	104 MAIN ST Elec Svc Existing Resi	104 MAIN ST Elec Svc Existing Residential pr6/2/17 AP2-YWO Total Cost Variance Met - Variance :97.5358 MIN.:-50 MAX.:150	Contributions-C01	107010	1
4N721280	PD-15 Blue Heron Rd Niantic/Install	PD-15 Blue Heron Rd Niantic/Install new OH/DB residential service AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
4E821053	Elec Svc Line Extension/Development	Elec Svc Line Extension/Development DESG (DN)	Contributions-C01	107010	1
1S821141	DM/36 HEUSTED DR OLD GRN: INST 3" S	DM/36 HEUSTED DR OLD GRN: INST 3" SEC RISER, 4/0 QPX, 200AMP 4W 120/208 AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
2L720526	THOMASTON - WATERTOWN AVE SUNOCO -	THOMASTON - WATERTOWN AVE SUNOCO - CHANGING SVC FROM OH TO DB AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1S621329	DL; 20 DEAN ST; REPLACE 2 FRNTR POL	DL; 20 DEAN ST; REPLACE 2 FRNTR POLES/NEW OH SEC RISER TO HH/DB SVC AP2-YWO Total Cost Variance Met - Variance :26.9456 MIN.:-50 MAX.:150	Contributions-C01	107010	1
1B722807	JS - 26 Linda La, Nw Frfld, Inst OH	JS - 26 Linda La, Nw Frfld, Inst OH/DB Svc (14H4) AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
1B921722	BM/ REPL PAD 872 WITH SAME	BM/ REPL PAD 872 WITH SAME NL-YWO Variance - NU Construction Labor	Contributions-C01	107010	1
2M924043	EJC 62 New Britain Rd, Berlin Repl	EJC 62 New Britain Rd, Berlin Repl 3ph Bank, Inst OH/DB Svc to Pedestal, M/L/C	Contributions-C01	107010	1
DG20LSSR	LODESTAR SAND RD CANAAN P#CD01400	LODESTAR SAND ROAD CANAAN P# CD01400 INT - 33391	Contributions-C01	252500	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
DG20LSWN	LODESTAR ENERGY P #CD01391	LODESAR ENERGY 1 PLATT HILL ROAD WINCHESTER, CT PROJECT #CD01391 INT - 33392	Contributions-C01	252500	1
2L720577	Canton--Gracy Rd. (180) 2061 Fronti	Canton--Gracy Rd. (180) 2061 Frontier to repl pole. Shft & inst 4/0 oh/ug svc AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
2M722004	(DF) 1/0 Tpx X-ing span, stub guyi	(DF) 1/0 Tpx X-ing span, stub guying, 4/0 CS 200A New Residential DESG (DN) AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
4E030999	MV-NEW DG PROJECT CD01409-01 FOR CP	MV-NEW DG PROJECT CD01409-01 FOR CP EAST HAMPTON SOLAR 1 LLC CL-YWO Variance - Contractor Labor	Contributions-C01	107010	1
5T030670	SOMERS, New OH/UG svc from P512 to	SOMERS, New OH/UG svc from P512 to 160 BATTLE ST AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
4N030570	MAV PD-5 Jerome Rd N. London/Instal	MAV PD-5 Jerome Rd N. London/Install +/- 110ft 4/0 3CT OH/DB from P# 1112 AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
5T922458	984 Russell Ave.Suffield New OH/DB	984 Russell Ave.Suffield New OH/DB service from P-435/Shed in field AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
4N130014	Sandpiper Point Rd, #3 Old Lyme/TL-	Sandpiper Point Rd, #3 Old Lyme/TL- UPGRADE OH XFMR@P#2226+INST NEW OH-DB SVC	Contributions-C01	107010	1
2M820093	JC/278 SPERRY RD. BETHANY/ NEW CV S	JC/278 SPERRY RD. BETHANY/ NEW CV SVC 4/0 POLE IN BACK YARD DO WITH WR3100314 AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
DG21GR29	GRE 29 WATERFORD, Waterford	GRE - 29 - Waterford Oil Mill Raod Waterford Project CD01028 / CS00352 LEG - 22774	Contributions-C01	252500	1
DG21LSNC	Lodestar North Canaan	Lodestar 81 E Main Street North Canaan CD01452 INT - 34494	Contributions-C01	252500	1
DG21SRNS	Silicon Ranch, N Stonington	Silicon Ranch N Stonington Cranberry Bog Road - N Stonington CT, Project No. CD01244 INT-35855	Contributions-C01	252500	1
2C720084	Salisbury Scovil move db pri back1	Salisbury Scovil move db pri back1 section ins new pri riser pad & service P2585 AP2-YWO Total Cost Variance Met - Variance :20.9923 MIN.:-50 MAX.:50	Contributions-C01	107010	1
DG22GREW	Reimb CD01682 Greenskies SE Windsor	Greenskies Clean Energy LLC Miller Rd - South East Windsor, Project No. CD01682 INT-41866	Contributions-C01	252500	1
DG22LSPT	Reimb CD01709 Lodestar Putnam	Lodestar Putnam CD01709 - INT-50381 116 Hawkins Road, Putnam, CT 06260 Maximo Work Order: 9820286 Customer: Jeffrey Macel LSE Scorpius LLC	Contributions-C01	252500	1
1S721520	RL:12 Harbor Rd; Electric Service N	RL:12 Harbor Rd; Electric Service New Residential SC OH/DB 350 Riser Line Set AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1
4E720596	MN 85 SILLIMANVILLE RD E HMPTN AT P	MN 85 SILLIMANVILLE RD E HMPTN AT P-1818 INS SECDY, XING POLE, OH SVC & MTR. AP2-YWO Total Cost Variance Met - Variance :117.088 MIN.:-50 MAX.:150	Contributions-C01	107010	1
4D721002	(DF) HH2638-A (I) 350 mcm svc 200A-	(DF) HH2638-A (I) 350 mcm svc 200A- New Residential UG w/CIAC Line Set AP1-YWO Total Cost Less Than 7K	Contributions-C01	107010	1