work_order_number	description	long_description	cost_element_group	ferc_account	percent
10117216	2016 sale- st lts town of cheshire	record the sale of street lights to the town of Cheshire value of approx -$464,633.15 Closing date 01/13/16	Salvage -M02	108040	1
10117217	sale of vernon st lts 319.3K	record the sale of street lights to the town of vernon value of approx 319.3K Closing date 05/13/16	Salvage -M02	108040	1
10117218	sale of Meriden st lts -1,072.7M	record the sale of street lights to the town of meriden value of approx 1,1072.7M Closing date 05/13/16	Salvage -M02	108040	1
10117219	Wolcott street light sale	record the sale of street lights to the town of Wolcott	Salvage -M02	108040	1
10117220	Street Lights for the town Cromwell	Record the sale of street lights to the town of Cromwell	Salvage -M02	108040	1
10117222	Street Light Sale Berlin	Record the sale of street lights to the town of Berlin	Salvage -M02	108040	1
10117223	Street Light Sale in Clinton	Record the sale of street lights to the town of Clinton	Salvage -M02	108040	1
10117224	Sale of Street Lights in East Lyme	Record the sale of street lights to the town of East Lyme	Salvage -M02	108040	1
10117225	Sale of Street Lights in Darien	Record the sale of street lights to the town of Darien	Salvage -M02	108040	1
10117226	Sale of Streetlights Simsbury	Record the sale of street lights to the town of Simsbury	Salvage -M02	108040	1
10117227	Sale of Street Lights West Hartford	Record the sale of street lights to the town of West Hartford	Salvage -M02	108040	1
10117228	2017 Sale of Streetlights Simsbury	Record the sale of street lights to the town of Simsbury	Salvage -M02	108040	1
10117229	2017 Sale of Streetlights Berlin	Record the sale of street lights to the town of Berlin	Salvage -M02	108040	1
10117230	Sale of Streetlights Mansfield	Record the sale of street lights to the town of Mansfield	Salvage -M02	108040	1
10117231	Sale of Streetlights Chester	Record the sale of street lights to the town of Chester	Salvage -M02	108040	1
10117232	Sale of Street Lights East Lyme	Record the sale of street lights to the town of East Lyme	Salvage -M02	108040	1
10117233	Sale of Streetlights Madison	Record the sale of street lights to the town of Madison	Salvage -M02	108040	1
10117234	Sale of Street Lights Wolcott	record the sale of street lights to the town of Wolcott	Salvage -M02	108040	1
10117235	Sale of Street Lights Old Saybrook	record the sale of street lights to the town of Old Saybrook	Salvage -M02	108040	1
10117236	Sale of Street Lights Granby	record the sale of street lights to the town of Granby	Salvage -M02	108040	1
10117237	Sale of Street Lights Ledyard	record the sale of street lights to the town of Ledyard	Salvage -M02	108040	1
10117238	Sale of Street Lights Seymour	record the sale of street lights to the town of Seymour	Salvage -M02	108040	1
10117240	Sale of Street Lights Thomaston	record the sale of street lights to the town of Thomaston 2018	Salvage -M02	108040	1
10117241	Sale of Streetlights Berlin 2018	Record the sale of street lights to the town of Berlin	Salvage -M02	108040	1
10117242	Sale of Streetlights Old Saybrook	Record the sale of street lights to the town of Old Saybrook 2018	Salvage -M02	108040	1
10117243	Sale of Streetlights Farmington	Record the sale of street lights to the town of Farmington 2018	Salvage -M02	108040	1
10117244	Sale of Streetlights Westbrook	Record the sale of street lights to the town of Westbrook 2018	Salvage -M02	108040	1
10117246	Sale of Streetlights Sprague	Record the sale of street lights Sprague	Salvage -M02	108040	1
10117247	Sale of Streetlights Sterling	Record the sale of street lights Sterling	Salvage -M02	108040	1
10117248	Sale of Streetlights Mansfield 2018	Record the sale of street lights for Mansfield 2018	Salvage -M02	108040	1
10117249	Sale of Street Lights Wethersfield	Record the sale of street lights for Wethersfield 2018	Salvage -M02	108040	1
10117250	Sale of Street Lights Canton	Record the sale of street lights for Canton 2018	Salvage -M02	108040	1
10117251	Sale of Streetlights Waterbury	Record the sale of street lights for Waterbury 2018	Salvage -M02	108040	1
10117252	Sale of StreetLights East Lyme 2018	Record the sale of street lights for East Lyme 2018	Salvage -M02	108040	1
10117253	Sale of Street lights Plymouth	Record the sale of street lights for Plymouth 2018	Salvage -M02	108040	1
10117255	SALE OF STREET LIGHTS WATERFORD	Record the sale of street lights for Waterford 2019	Salvage -M02	108040	1
10117256	SALE OF STREET LIGHTS GUILFORD	Record the sale of street lights for Guilford 2019	Salvage -M02	108040	1
10117259	Sale of Streetlights to Middlefield	Record the sale of street lights for Middlefield 2019	Salvage -M02	108040	1
10117260	Sale of Streetlights WESTON	Record the sale of street lights for WESTON 2019	Salvage -M02	108040	1
1B321594	TB- 772 MONROE TPKE POLE 268 INSTAL	TB- 772 MONROE TPKE POLE 268 INSTALL CV SERVICE	Salvage -M02	108040	1
1B422408	ESO hattertown rd monroe tree broke	ESO hattertown rd monroe tree broke x arm	Salvage -M02	108040	1
1B520312	BR Hut Hill Rd, Bridgewater ESO Wor	BR Hut Hill Rd, Bridgewater ESO Work #3217 Completed in Field	Salvage -M02	108040	1
1B520862	BR Rt 39 New Fairfield Replaced Xfr	BR Rt 39 New Fairfield Replaced Xfrm Completed in Field	Salvage -M02	108040	1
1B521850	Meadows End Rd, Monroe, p.#206 poor	Meadows End Rd, Monroe, p.#206 poor condition should be replaced AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B521883	BR 153 Wilton Rd Ridgefield Tree vs	BR 153 Wilton Rd Ridgefield Tree vs Line Completed in Field	Salvage -M02	108040	1
1B521909	ESO Mill Plain Rd DNBY- CarVsPole55	ESO Mill Plain Rd DNBY- CarVsPole55 Braced-Frontier to Set New 8/21/15 AP3-YWO Resource Variance Met- Labor 13 <= 32 OR 112.2 <= 30 And Contractor $1546.34 <= 2000	Salvage -M02	108040	1
1B522254	Key Rock Rd, Newtown, pole top fire	Key Rock Rd, Newtown, pole top fire need to repl p#2477 40/2 NOTIFY# 496101 AP2-YWO Total Cost Variance Met - Variance :100.357 MIN.:-50 MAX.:150	Salvage -M02	108040	1
1B522296	AF - 3PA-CONV#310934 - Replace pole	AF - 3PA-CONV#310934 - Replace pole 2007 pr TS 1/28 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B522443	RM-101395, REPLACE CABLE, Scenic Hi	RM-101395, REPLACE CABLE, Scenic Hill LN pad 46 & 47- Monroe CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
1B620051	CB - CDOT 34-305 & 345 Move 1	CB - CDOT 34-305 & 345 Move 1 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
1B620115	RR- 104 Forty Acre Mtn Rd Danbury,	RR- 104 Forty Acre Mtn Rd Danbury, ATT p #4268 needs to be replaced PR01/20/16 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B620199	15 BATES PL Elec Svc New Residenti	15 BATES PL Elec Svc New Residential PR2/4/16	Salvage -M02	108040	1
1B620226	DP, WASH 165 SHEARER RD, PRIORITY	DP, WASH 165 SHEARER RD, PRIORITY REJECT POLE#3474, 1PH , ANCHOR CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
1B620261	44 KENOSIA AVE Elec Maint Trouble C	44 KENOSIA AVE Elec Maint Trouble Call - Repairs/Obsolescence OH PR2/17/16 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B620362	NORTH ST replace recloser 22N5-71	NORTH ST replace recloser 22N5-71s Y-17131-2016 pole 5024 PR3/2/16	Salvage -M02	108040	1
1B620819	JDB WEBATUCK RD SHERMAN COMPLETED,	JDB WEBATUCK RD SHERMAN COMPLETED, ESO 5/7 9A pole 929 AP2-YWO Total Cost Variance Met - Variance :63.2336 MIN.:-50 MAX.:150	Salvage -M02	108040	1
1B621325	SH-Convo#342618-(MakeReadyNonReimb)	SH-Convo#342618-(MakeReadyNonReimb) - Fibertech Parent Convo#338911 AP2-YWO Total Cost Variance Met - Variance :-30.9342 MIN.:-40 MAX.:40	Salvage -M02	108040	1
1B621534	ROX, 142 EAST FLAG SWAMP, TEL REPL	ROX, 142 EAST FLAG SWAMP, TEL REPL POLE. HANG POT AND OH/DB SVC FOR GATE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B622090	WOOD, 120 WEST LAKE RD, OH SVC CHEC	WOOD, 120 WEST LAKE RD, OH SVC CHECK EXISTING DROP TO 2 , SET METER AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B622145	RM 39 Putnam Park Rd Bethel PER SH	RM 39 Putnam Park Rd Bethel PER SHOOTER NEED CUT AND KICK ALSO TREE TRIMMING AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B622282	RL Black Rock Tpke, Redding replace	RL Black Rock Tpke, Redding replace DB primary cable from Riser P#969 to PAD200 AP2-YWO Total Cost Variance Met - Variance :1.7385 MIN.:-40 MAX.:40	Salvage -M02	108040	1
1B622283	PH; 661 Redding Rd, Redding, replac	PH; 661 Redding Rd, Redding, replace DB primary from Riser P#1181 to PAD3 AP2-YWO Total Cost Variance Met - Variance :3.1947 MIN.:-40 MAX.:40	Salvage -M02	108040	1
1B720029	Electric Service Existing Residenti	Electric Service Existing Residential Overhead (PHD)	Salvage -M02	108040	1
1B720072	9A COMPLETED, 124 Calhoun, Washingt	9A COMPLETED, 124 Calhoun, Washington, car vs. pole 1773, TEL REPLACED,SHIFTED AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B720073	9A COMPLETED23 Hooppole Hill, Woodb	9A COMPLETED23 Hooppole Hill, Woodbury, car vs. pole FRONTIER REPLACED POLE W5 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B720145	CDOT 34-313 Danbury - CIS#2 - relo	CDOT 34-313 Danbury - CIS#2 - reloc service to Wells Fargo JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
1B720242	ESO, White Deer Rocks Rd, Woodbury	ESO, White Deer Rocks Rd, Woodbury - Car vs Pole 1215 AP2-YWO Total Cost Variance Met - Variance :116.5616 MIN.:-50 MAX.:150	Salvage -M02	108040	1
1B720417	OLD BROOKFIELD RD Elec Maint Troub	OLD BROOKFIELD RD Elec Maint Trouble Call - Repairs/Obsolescence DB pr3/9/17 CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
1B720430	BLITZ, NM, OLD PARK LN, POLE #10, E	BLITZ, NM, OLD PARK LN, POLE #10, ES SHIFT TEL HAS SET, DBL POLE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B720453	Brookfield, Meadow Brook Rd - Front	Brookfield, Meadow Brook Rd - Frontier pole shift 1384 pr3/11/17 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B720502	COMPL IN FIELD; REPL 100AMP C/O @ P	COMPL IN FIELD; REPL 100AMP C/O @ PL 2622	Salvage -M02	108040	1
1B720873	TB- ELGIN AVE BETHEL SHIFT FRONTIER	TB- ELGIN AVE BETHEL SHIFT FRONTIER P 30 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B720883	23 SIMPAUG TPKE Elec Svc Existing	23 SIMPAUG TPKE Elec Svc Existing Residential pr4/27/17 AP2-YWO Total Cost Variance Met - Variance :66.3019 MIN.:-50 MAX.:150	Salvage -M02	108040	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
1B720920	JS - 50 Sawmill Rd, Danb, Inst\Rem	JS - 50 Sawmill Rd, Danb, Inst\Rem OH/DB Svc (28M3) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B720968	CB - CDOT - 34-305 & 345 Move 2	CB - CDOT - 34-305 & 345 Move 2 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
1B720975	116 N LAKE SHORE DR Elec Svc New R	116 N LAKE SHORE DR Elec Svc New Residential AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B721060	104 MAIN ST Elec Svc Existing Resi	104 MAIN ST Elec Svc Existing Residential pr6/2/17 AP2-YWO Total Cost Variance Met - Variance :97.5358 MIN.:-50 MAX.:150	Salvage -M02	108040	1
1B721538	2 ROCKWELL RD extend primary pole l	2 ROCKWELL RD extend primary pole line install prim. riser to pad + svc CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
1B721557	BR 121 Lantern Park Ln N Southbury	BR 121 Lantern Park Ln N Southbury Yellow Tag CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
1B721855	36 HAYES LN relocate to mid-span E	36 HAYES LN relocate to mid-span Existing Residential Overhead AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B721941	JS - 3 East St, Danb, Inst\Rem OH S	JS - 3 East St, Danb, Inst\Rem OH Svc (11A76) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B721946	JS - 17 Beckett St, Danb, Inst\Rem	JS - 17 Beckett St, Danb, Inst\Rem OH Svc (28M1) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B721957	JS - 4 Woodview Dr, Brkfld, Inst\Re	JS - 4 Woodview Dr, Brkfld, Inst\Rem OH Svc (14H3) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B721958	JS - 25 Woodview Dr, Brkfld, Inst\R	JS - 25 Woodview Dr, Brkfld, Inst\Rem OH Svc (14H3) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B722028	JS - 6 Hewlett Rd, Nw Frfld, Inst\R	JS - 6 Hewlett Rd, Nw Frfld, Inst\Rem OH Svc (28M2) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B722973	JS - Larson Dr, Danb, Rem OH Neut,	JS - Larson Dr, Danb, Rem OH Neut, Inst OH Sec (28M13) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B820016	25 CREST RD Electric Service Existi	25 CREST RD Electric Service Existing Residential Overhead AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B821681	SH-Convo#672962-MakeReadyNonReimib	SH-Convo#672962-MakeReadyNonReimib Parent Convo#657857 NO AWOCS-AWOCS REASON CODE AND DESCRIPTION NOT FOUND.	Salvage -M02	108040	1
1B821744	JS - 47 West Wooster St, Danb, Inst	JS - 47 West Wooster St, Danb, Inst\Rem OH Svc (11A74) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1B822375	CDOT 18-136 - Brookfield Streetscap	CDOT 18-136 - Brookfield Streetscape - Relocate 205, 206 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
1B921722	BM/ REPL PAD 872 WITH SAME	BM/ REPL PAD 872 WITH SAME NL-YWO Variance - NU Construction Labor	Salvage -M02	108040	1
1B922289	101395 1552 Replace cable from P	101395 1552 Replace cable from POLE 1296 to PAD 316 Old Field Ln, Redding CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
1B923313	5 HIGH ST Electric Service Existing	5 HIGH ST Electric Service Existing Residential Overhead pr10/24/19 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1G520706	DM/6 Grove ST COS COB: PRIORITY DE	DM/6 Grove ST COS COB: PRIORITY DESG (IFOH) - POLE#119 CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
1G520761	DM/107 DOUBLING RD GREENWICH: RELOC	DM/107 DOUBLING RD GREENWICH: RELOCATE OH LINES TO UNDERGROUND AP2-YWO Total Cost Variance Met - Variance :-23.6492 MIN.:-50 MAX.:50	Salvage -M02	108040	1
1G620304	RL 30 Butternut Hollow/P#70537/Tree	RL 30 Butternut Hollow/P#70537/Tree broke pole,see ticket/Alex M.	Salvage -M02	108040	1
1G620491	RL:35 Mooreland Rd; Elec Svc New Re	RL:35 Mooreland Rd; Elec Svc New Residential IT 600 amp Meter DESG NO AWOCS-AWOCS REASON CODE AND DESCRIPTION NOT FOUND.	Salvage -M02	108040	1
1G620693	Elec Svc New Com/Ind IT Meter DESG	Elec Svc New Com/Ind IT Meter DESG (DN) AP2-YWO Total Cost Variance Met - Variance :-18.0765 MIN.:-40 MAX.:40	Salvage -M02	108040	1
1G621155	RL:120 Valley Dr::Elec Svc New Resi	RL:120 Valley Dr::Elec Svc New Residential DESG 40/2 Pole 36" Silo (DN) AP3-YWO Resource Variance Met- Labor 14 <= 32 OR 62.62 <= 30 And Contractor $1228.29 <= 2000	Salvage -M02	108040	1
1G621163	DM/32 MEETING HOUSE RD GRN: REPL P.	DM/32 MEETING HOUSE RD GRN: REPL P.80483 & 73715 - CUSTOMER COMPLAINT AP2-YWO Total Cost Variance Met - Variance :-35.0579 MIN.:-40 MAX.:40	Salvage -M02	108040	1
1G621184	RL:ZACCHEUS MEAD GREENWICH 9A POLE	RL:ZACCHEUS MEAD GREENWICH 9A POLE 73577 ESO AP2-YWO Total Cost Variance Met - Variance :40.0956 MIN.:-50 MAX.:50	Salvage -M02	108040	1
1G621297	RL:10 Glenville Rd: Verizon replace	RL:10 Glenville Rd: Verizon replaced pole 68060 VZ 5 50/2 Car vs pole 9A CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
1M320139	588, NF, DP, Bear Mt Rd, AT&T to R	588, NF, DP, Bear Mt Rd, AT&T to Repl Detriorated pole 1315 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1M420090	KENT, CAMEL HILL RD,CAMP FRANCIS ,	KENT, CAMEL HILL RD,CAMP FRANCIS , DEMO 2 OF 4 REM OH SECSVC METER RANGER CABIN AP1 - WO TOTAL COST LESS THAN 7K	Salvage -M02	108040	1
1N030555	JDB 6/7: LINDEN HTS NORWALK:POLE#94	JDB 6/7: LINDEN HTS NORWALK:POLE#945 REPLACED 50 KVA AND ELBOW ARRESTOR	Salvage -M02	108040	1
1N221114	JDB 10 ARCH ST,NWLK TRUCK HIT POLE	JDB 10 ARCH ST,NWLK TRUCK HIT POLE #9577 SEE TT INFO 06/01/12 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1N321978	JDB 165 GRUMMAN AVE NWLK P32758 Ele	JDB 165 GRUMMAN AVE NWLK P32758 Elec Proj Maintain Voltage Annual DESG (DK) CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
1N322459	JES: 3 DUKE PL. NORWALK, CAR VS POL	JES: 3 DUKE PL. NORWALK, CAR VS POLE MADE TEMP REPAIRS, P# 9012 SEE TT 11-15-13 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1N422555	AF-Elec Proj Cable Repl Spec - Butl	AF-Elec Proj Cable Repl Spec - Butler Ln - New Canaan, CT CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
1N520002	RM- 101395, Cable Replacement - Mes	RM- 101395, Cable Replacement - Messex Ln - Weston	Salvage -M02	108040	1
1N620110	LD WEST CEDAR ST NORWALK RECONDUCTO	LD WEST CEDAR ST NORWALK RECONDUCTOR PRI 24A10-73S-24A10-92T TD 941 POLE#23020 CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
1N620657	CONV 484563 - RM-CDOT 158-0211, PHA	CONV 484563 - RM-CDOT 158-0211, PHASE I, NEWTOWN TRPK / RT 15 - WESTPORT JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
1N620810	RM 159 Godfrey Rd East Weston Repl	RM 159 Godfrey Rd East Weston Replace pole 31846 per tele request !!! AP2-YWO Total Cost Variance Met - Variance :24.4577 MIN.:-50 MAX.:150	Salvage -M02	108040	1
1N620926	LD 14 MAIN STREET NOR PARKING LOT R	LD 14 MAIN STREET NOR PARKING LOT RPL POLE#27127 RPL TO LED'S FROM HPS LIGHTS AP2-YWO Total Cost Variance Met - Variance :42.7862 MIN.:-50 MAX.:50	Salvage -M02	108040	1
1N620945	LD WESTPORT NETWORK RPL SEC MAIN'S	LD WESTPORT NETWORK RPL SEC MAIN'S & RECRAB 3 MH#'S TO TYPE B PROJ #103358-13 AP2-YWO Total Cost Variance Met - Variance :2.4156 MIN.:-10 MAX.:10	Salvage -M02	108040	1
1N621145	JDB EAST AVE NWLK P2890 RMV ARMLESS	JDB EAST AVE NWLK P2890 RMV ARMLESS INSTALL 6' XARM OH DESG (AROH) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1N621166	JES; 345 NEWTOWN TPKE, WESTON-BROKE	JES; 345 NEWTOWN TPKE, WESTON-BROKEN P#31868 & 31870 08/09/16	Salvage -M02	108040	1
1N621292	JES; WILLARD RD. NWLK.; IR INSP. -	JES; WILLARD RD. NWLK.; IR INSP. - Minor DESG (IFOH) - POLE 13273 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1N621466	AJC BEACHSIDE AVE WSPT RPL DB PRI	AJC BEACHSIDE AVE WSPT RPL DB PRI FROM POLE#25131 TO PAD#127 PROJ#101395-09 CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
1N621475	AJC BUTLER LN NC INS PIPE& RPL DB	AJC BUTLER LN NC INS PIPE& RPL DB PRI FROM POLE#24732 TO PAD#221 PROJ#101395-09 AP2-YWO Total Cost Variance Met - Variance :29.9076 MIN.:-40 MAX.:40	Salvage -M02	108040	1
1N621689	JDB 18 OX YOKE LN NWLK P9366 EXTEND	JDB 18 OX YOKE LN NWLK P9366 EXTEND PRI INS 50KVA & OH/DB SVC DESG (DN) AP2-YWO Total Cost Variance Met - Variance :-19.5236 MIN.:-40 MAX.:40	Salvage -M02	108040	1
1N621850	RM -CD00667, Recloser @ P-4977 Knap	RM -CD00667, Recloser @ P-4977 Knapp St - Norwalk AP2-YWO Total Cost Variance Met - Variance :23.7919 MIN.:-30 MAX.:30	Salvage -M02	108040	1
1N621866	AJC 6 KELLER LN WSPT MIDTAP Electri	AJC 6 KELLER LN WSPT MIDTAP Electric Service Existing Residential Overhead P9106	Salvage -M02	108040	1
1N621985	RM 10 Ridge Ln Weston Replace Exis	RM 10 Ridge Ln Weston Replace Existing Residential Overhead svc	Salvage -M02	108040	1
1N720013	JDB FILLOW ST NWLK P1746 FUSE COORD	JDB FILLOW ST NWLK P1746 FUSE COORDINATION Annual DESG (DR) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1N720608	JDB 18 FLICKER LN NWLK SHIFT POLE 6	JDB 18 FLICKER LN NWLK SHIFT POLE 6545 INSTALL New OH/DB Residential DESG (DN) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1N720842	JDB ESO 4/26/17 WESTPORT - 9 CRAWF	JDB ESO 4/26/17 WESTPORT - 9 CRAWFORD RD P6838 REPLACE XTRANS AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1N720847	ESO 9A 4/29/17-WESTPORT = 22 MAPLE	ESO 9A 4/29/17-WESTPORT = 22 MAPLE AVE, P#26017 !!!!! AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1N720848	JDB/P# 33766/REPLACED 50KVA XFRMR/I	JDB/P# 33766/REPLACED 50KVA XFRMR/INSTALLED 100 AMP CUTOUT & BRACKET/5-31 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
1N720860	JES; 31A8 Capacitor Solution - New	JES; 31A8 Capacitor Solution - New Canaan Silvermine Rd PL 27... AP2-YWO Total Cost Variance Met - Variance :4.9118 MIN.:-40 MAX.:40	Salvage -M02	108040	1
1N720986	JES; 659 DANBURY RD. WILTON. REPLAC	JES; 659 DANBURY RD. WILTON. REPLACE BAD POLE & RE ROUT LINES. 19024.. AP3-YWO Resource Variance Met- Labor 8 <= 32 OR -19.14 <= 30 And Contractor $1030.89 <= 2000	Salvage -M02	108040	1
1N721071	JDB SPRING HILL AVE,NWLK - 9A HBA R	JDB SPRING HILL AVE,NWLK - 9A HBA REPL POLE#26 07/19/17 AP3-YWO Resource Variance Met- Labor 23 <= 32 OR 37.03 <= 30 And Contractor $0 <= 2000	Salvage -M02	108040	1
1N721075	JDB 144 MAIN ST, NORWALK- BAD DB PR	JDB 144 MAIN ST, NORWALK- BAD DB PRIM P#20241 07/19/17 AP2-YWO Total Cost Variance Met - Variance :6.2892 MIN.:-50 MAX.:50	Salvage -M02	108040	1
1N721098	JES; 66 WHITE FALL LN NEW CANAAN.;	JES; 66 WHITE FALL LN NEW CANAAN.; Elec Svc Existing Residential POLE 8525... AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1N721146	JES; 269 MILLSTONE RD. WILTON.; REL	JES; 269 MILLSTONE RD. WILTON.; RELOCATE OH SVC. POLE 21268... AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1N721672	AJC 54 WILTON RD WSPT REPLACE POLE	AJC 54 WILTON RD WSPT REPLACE POLE 1205 INSTALL P RISER & PAD REM P DB PRI & DH	Salvage -M02	108040	1
1N721713	RSO; 11/24; BAYBERRY LN WSPT; REFER	RSO; 11/24; BAYBERRY LN WSPT; REFER TO AWC TO REPL #2 SVC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1N721862	9A !!!!!!!!!!RSO 12/23; NEWTOWN TP	9A !!!!!!!!!!RSO 12/23; NEWTOWN TPKE WESTON; CAR V P31920-21 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1N820137	LD 41 WOLFPIT AVE NORWALK RECONDUCT	LD 41 WOLFPIT AVE NORWALK RECONDUCTOR LINE FROM ENTRANCE POLE#23558 AP2-YWO Total Cost Variance Met - Variance :-2.4311 MIN.:-30 MAX.:30	Salvage -M02	108040	1
1N820466	MJP - CD00348 - 102-363 - (4)Phase	MJP - CD00348 - 102-363 - (4)Phase 1: Removal of Existing OH Pole Line JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
1N820554	MJP - CD00348 - 102-363 - (3)Phase	MJP - CD00348 - 102-363 - (3)Phase 1: Electrical UG work required JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
1N820556	MJP - CD00348 - 102-363 - (7)Phase	MJP - CD00348 - 102-363 - (7)Phase 2: Electrical UG work required NO AWOCS-AWOCS REASON CODE AND DESCRIPTION NOT FOUND.	Salvage -M02	108040	1
1N821098	MJP - CD00348 - 102-363 - (5)Phase	MJP - CD00348 - 102-363 - (5)Phase 1: OH Work, Relocate P. 12008 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
1N821115	JES; 610 OLD STAMFORD RD. NEW CANAA	JES; 610 OLD STAMFORD RD. NEW CANAAN.; Elec Svc Existing Residential pl 671...	Salvage -M02	108040	1
1N821513	LD 26 ORLANDO PL NORWALK TROUBLE R	LD 26 ORLANDO PL NORWALK TROUBLE REPORT, POLE 6855 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S031963	MJP/1335 E Main St/STM/Relocate Str	MJP/1335 E Main St/STM/Relocate Str Light P 11720 & Other Misc Work JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
1S032158	MJP/1290 E Main St/STM/Install 50'	MJP/1290 E Main St/STM/Install 50' Poles 8169 & 5797 for Clearance over Weed Ave JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
1S420578	RM- CDOT 135-307, Temp Relocate Pol	RM- CDOT 135-307, Temp Relocate Poles 5797, 5798 E MAIN ST - STAMFORD JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
1S421351	CD00340-00 REPLACE 1G18 CABLE w/1	CD00340-00 REPLACE 1G18 CABLE w/1000MCM MH696 to MH698 CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
1S520964	DL Relocate OH service	DL Relocate OH service AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S521266	PH; 13 Juniper Rd, Darien Relocate	PH; 13 Juniper Rd, Darien Relocate OH facilities to UG for customer CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
1S521599	DL; ESO 9A FAIRFIELD AVE; P#1736/	DL; ESO 9A FAIRFIELD AVE; P#1736/REPLACE RECLOSER - UPPER UNIT-**YELLOW TAG** AP2-YWO Total Cost Variance Met - Variance :-30.3396 MIN.:-40 MAX.:40	Salvage -M02	108040	1
1S521821	RM- CDOT 135-307, Temp Relocate Pol	RM- CDOT 135-307, Temp Relocate Poles Boston post Rd - DARIEN JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
1S620343	PH; 0 Shadbush Ln/P#13752/Tree brok	PH; 0 Shadbush Ln/P#13752/Tree broke pole/Rep 25 kVa & cutout/See TT/Alex M.	Salvage -M02	108040	1
1S620701	RL BELLE HAVEN REMOVE OVERHEAD ON M	RL BELLE HAVEN REMOVE OVERHEAD ON MAYO AVE AP3-YWO Resource Variance Met- Labor 35 <= 32 OR -37.25 <= 30 And Contractor $1731.29 <= 2000	Salvage -M02	108040	1
1S620993	PH; 151 BROOKSIDE RD; INSTALL 200AM	PH; 151 BROOKSIDE RD; INSTALL 200AMP DB, REMOVE 100AMP DB SERVICE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S621329	DL; 20 DEAN ST; REPLACE 2 FRNTR POL	DL; 20 DEAN ST; REPLACE 2 FRNTR POLES/NEW OH SEC RISER TO HH/DB SVC AP2-YWO Total Cost Variance Met - Variance :26.9456 MIN.:-50 MAX.:150	Salvage -M02	108040	1
1S720173	PH; 16 RAIDERS LN; INSTALL 400AMP D	PH; 16 RAIDERS LN; INSTALL 400AMP DB SERVICE, REMOVE OH POLE LINE/SERVICE AP2-YWO Total Cost Variance Met - Variance :56.1339 MIN.:-50 MAX.:150	Salvage -M02	108040	1
1S720200	DM/461 STANWICH RD GREENWICH: CAR V	DM/461 STANWICH RD GREENWICH: CAR VS POLE 73690-S AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S720372	DL; 16 EMERY DR E; REPLACE BACKYARD	DL; 16 EMERY DR E; REPLACE BACKYARD POLE AND INSTALL NEW OH/DB SVC RISER AP2-YWO Total Cost Variance Met - Variance :53.9906 MIN.:-50 MAX.:150	Salvage -M02	108040	1
1S720461	RL:11 Watch Hill Dr:Elec Existing R	RL:11 Watch Hill Dr:Elec Existing Residential OH/DB Remove span Tpx & OH service AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S720478	DM/8 PARK AVE GREENWICH: INTERCEPT	DM/8 PARK AVE GREENWICH: INTERCEPT EXIST DB SVC, 4/0 DB SVC, 200AMP AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S720506	DL; 970 STILLWATER RD; TRANSFER TO	DL; 970 STILLWATER RD; TRANSFER TO FRONTIER POLE 113347/NEW OH/DB RISER AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S720532	PH; 3/4/17 ESO - 1070 HIGH RIDGE RD	PH; 3/4/17 ESO - 1070 HIGH RIDGE RD STAMFORD CAR VS POLE# 9654 CASE# 1703040002 EW-YWO Variance - Emergent Work	Salvage -M02	108040	1
1S720569	RL:Ettl Ln: Replace poles 79977, 79	RL:Ettl Ln: Replace poles 79977, 79976 Install 3 spans 1/0 tpx remove open wire AP2-YWO Total Cost Variance Met - Variance :21.7787 MIN.:-50 MAX.:50	Salvage -M02	108040	1
1S720604	BK 1011 WASHINGTON BLVD INSTALL 3RD	BK 1011 WASHINGTON BLVD INSTALL 3RD TRANSFORMER IN LOOP 300KVA AP2-YWO Total Cost Variance Met - Variance :37.0399 MIN.:-40 MAX.:40	Salvage -M02	108040	1
1S720834	DL; WASHINGTON BLVD; FAULT TO 3 STA	DL; WASHINGTON BLVD; FAULT TO 3 STAMFORD LIGHTS AP2-YWO Total Cost Variance Met - Variance :32.5896 MIN.:-50 MAX.:50	Salvage -M02	108040	1
1S720997	PH; 165 BOUTON ST W; INSTALL NEW 20	PH; 165 BOUTON ST W; INSTALL NEW 200AMP DB; REPLACE POLE 925 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S721003	DL; 2 OPPER RD; Electric Service Ex	DL; 2 OPPER RD; Electric Service Existing Residential Overhead AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S721018	DM/59 HARDING RD OLD GRN: INST 1/0	DM/59 HARDING RD OLD GRN: INST 1/0 TPX FROM P.1883 TO P.1884 SHIFT 2 SVCS AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S721069	PH; 51 LENOX AVE; Replace OH Servic	PH; 51 LENOX AVE; Replace OH Service AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S721128	Interlaken - Cap inspection and rep	Interlaken - Cap inspection and repair @ pole 689 schedule ASAP-LOAD RELIEF AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S721154	RL 75 Stonehedge Dr S, Grn Replace	RL 75 Stonehedge Dr S, Grn Replace #4 AL OH service with 1/0 TPX AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S721192	RL:174 MANSFIELD AVE: 9A 5/20/17- D	RL:174 MANSFIELD AVE: 9A 5/20/17- DARIEN - NUE P # 36 45/2 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S721203	DL; SYLVAN KNOLL RD; REPLACE POLE 5	DL; SYLVAN KNOLL RD; REPLACE POLE 597 & 598/SHIFT PRIMARY CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
1S721300	DL; 3 WEED CIR; 1PH UG Svc - Replac	DL; 3 WEED CIR; 1PH UG Svc - Replace Exist w/ UV4/0AL3CT - APPT NEEDED AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S721343	DM/DAVIS & LE GRANDE AVE GRN: P.679	DM/DAVIS & LE GRANDE AVE GRN: P.67972 REPLACE XARMS AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S721357	RL:Byram Shore Rdf:9A DIGUP- 245 BY	RL:Byram Shore Rdf:9A DIGUP- 245 BYRAM SHORE RD GREENWICH Riser Pole 81785 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S721416	DM/STRICKLAND RD COS COB: 11R56 CAB	DM/STRICKLAND RD COS COB: 11R56 CABLE FAILURE/REPLACE CABLE AT MH117 TO MH127 AP2-YWO Total Cost Variance Met - Variance :8.429 MIN.:-20 MAX.:20	Salvage -M02	108040	1
1S721431	RL:1 Lillian Ter: Replace OH Servic	RL:1 Lillian Ter: Replace OH Service 110' #2 Tpx AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S721482	PH; 55 WOODLEDGE RD; Replace OH Ser	PH; 55 WOODLEDGE RD; Replace OH Service & LOOSE HOUSE KNOB AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S721524	DL; RIVERBANK RD; REPLACE/RELOCATE	DL; RIVERBANK RD; REPLACE/RELOCATE 2 POLES FOR STAMFORD BRIDGE CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
1S721577	21 LEEDS ST STAMFORD/ REPLACED SERV	21 LEEDS ST STAMFORD/ REPLACED SERVICE WITH 40' #2 - ALL WORK COMPLETE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S721581	RL:59 View St West Electric Service	RL:59 View St West Electric Service Existing Residl OH Install 3 meters remove 2 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S721624	DL; 33 ELM TREE PL, STAMFORD: REPLA	DL; 33 ELM TREE PL, STAMFORD: REPLACE #2 100FT SERVICE- ALL WORK COMPLET AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
1S722078	DM/600 NORTH ST GRN: RELOCATE (2) P	DM/600 NORTH ST GRN: RELOCATE (2) POLES FOR 3-LOT SUBDIVISION AP2-YWO Total Cost Variance Met - Variance :-37.3145 MIN.:-50 MAX.:50	Salvage -M02	108040	1
1S722546	RL: 20 Edgar Rd:Replace #1 AL prim	RL: 20 Edgar Rd:Replace #1 AL primary, cutout & arrester already replaced AP2-YWO Total Cost Variance Met - Variance :-34.5233 MIN.:-50 MAX.:50	Salvage -M02	108040	1
1S811292	RL;159 Breezy Hill Rd; Elec Svc Exi	RL;159 Breezy Hill Rd; Elec Svc Existing Residential DESG (DN) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S820537	COMP. 05/06/2019 STM Muni FLR ir@	COMP. 05/06/2019 STM Muni FLR ir@ POLE 2143 NO PWR UG- NEEDS FIXTURE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S821300	RL:150 Old Kings Hwy; Electric Serv	RL:150 Old Kings Hwy; Electric Service Existing Residential Overhead 110' #2 tpx AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S821317	SH-Convo#671325-MakeReadyReimb - Ci	SH-Convo#671325-MakeReadyReimb - Cingular WL Parent Convo#655137 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
1S821939	CM-Conv#673174-MakeReadyNonReimb-MC	CM-Conv#673174-MakeReadyNonReimb-MCI Parent Conv#657452 NO AWOCS-AWOCS REASON CODE AND DESCRIPTION NOT FOUND.	Salvage -M02	108040	1
2C420241	(3 or more) - Salisbury-White Hollo	(3 or more) - Salisbury-White Hollow Rd-4L09 Rehab-Rec (10 poles,site del) KEEP	Salvage -M02	108040	1
2C620204	rpl ples relocate 1xfrmr ins 3phase	rpl ples relocate 1xfrmr ins 3phase banl and oh svc camp sloane indian mt rd AP2-YWO Total Cost Variance Met - Variance :-.1457 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2C620304	PT Conv# 461290-MakeReadyNonReimb-C	PT Conv# 461290-MakeReadyNonReimb-Comcast-ParentConv# 450571 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2C720084	Salisbury Scovil move db pri back1	Salisbury Scovil move db pri back1 section ins new pri riser pad & service P2585 AP2-YWO Total Cost Variance Met - Variance :20.9923 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2C720129	rpl poles ins xfrmr bank ins new oh	rpl poles ins xfrmr bank ins new oh svc 2607 south canaan rd fv DC-YWO Variance - Design/Construction	Salvage -M02	108040	1
2C720130	replace and relocate svc from oh to	replace and relocate svc from oh to db pole 406 upper main st sharon appt needed AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2C720133	ins new db svc to beckley furnace l	ins new db svc to beckley furnace lower rd north canaan AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2C820221	SW CDOT 99-114/115 MAIN ST N CANAAN	SW CDOT 99-114/115 MAIN ST N CANAAN (RR XING IMPROVEMENTS) JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2L420582	Kent, 373 Kent Hollow Rd -- ins new	Kent, 373 Kent Hollow Rd -- ins new db pri to pad P3092- APPT Wed 10/7 w/Coleman AP2-YWO Total Cost Variance Met - Variance :49.4741 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2L420778	SW DOT PROJ 162-145 HOLABIRD AVE W	SW DOT PROJ 162-145 HOLABIRD AVE WINCHESTER BRIGE REPL (TEMP RELOC) CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
2L520052	New Htfd, Gillette Rd, - (3 or mor	New Htfd, Gillette Rd, - (3 or more) 5R1 - (CUST CPLT) See Skt.- Recond w/ TW	Salvage -M02	108040	1
2L520353	BETHLEHEM,76 & 78 CRANE HOLLOW RD//	BETHLEHEM,76 & 78 CRANE HOLLOW RD//EXISTING SVC CHANGES & UPGRADES// OH TO DB AP2-YWO Total Cost Variance Met - Variance :35.2001 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2L520390	PLYMOUTH,GREYSTONE RD/SHIFT RED TAG	PLYMOUTH,GREYSTONE RD/SHIFT RED TAGGED PHONE POLES//P#322 & P#319//POLES ARE SET	Salvage -M02	108040	1
2L520432	WINCHESTER POLE 8172 70 MH PDL 435	WINCHESTER POLE 8172 70 MH PDL 435631 - COMPLETED 3/18/16 HAR	Salvage -M02	108040	1
2L520433	WINCHESTER POLE 8160 70 MH PDL 435	WINCHESTER POLE 8160 70 MH PDL 435631 - COMPLETED 3/18/16 HAR	Salvage -M02	108040	1
2L620133	Burlington, Milford St - AWC/ 2/5/	Burlington, Milford St - AWC/ 2/5/ (9A) AP2-YWO Total Cost Variance Met - Variance :59.231 MIN.:-50 MAX.:150	Salvage -M02	108040	1
2L620302	cornwall, dibble hill rmv oh R.O.	cornwall, dibble hill rmv oh R.O.W ins db up driveway to upgraded svc AP2-YWO Total Cost Variance Met - Variance :23.2749 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2L620485	WARREN,39 BLISS RD//REMOVE POLE LIN	WARREN,39 BLISS RD//REMOVE POLE LINE & INSTALL DB PRIMARY, PAD &SWITCH// AP2-YWO Total Cost Variance Met - Variance :-3.7348 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2L620873	LITCHFIELD,12 NORFOLK RD// INSTALL	LITCHFIELD,12 NORFOLK RD// INSTALL NEW 300 KVA DB XFMRFOR NEW MUSIC CENTER// AP3-YWO Resource Variance Met- Labor 11 <= 32 OR 27.01 <= 30 And Contractor $0 <= 2000	Salvage -M02	108040	1
2L621090	ESO 10/27 BETHLEHEM, PADDY HOLLOW R	ESO 10/27 BETHLEHEM, PADDY HOLLOW RD, CAR VPOLE B13 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2L720118	Winsted, 170 Williams Ave MK CONV#4	Winsted, 170 Williams Ave MK CONV#488774-MAKEREADYNON-REIMB AP2-YWO Total Cost Variance Met - Variance :-28.6419 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2L720357	Winchester--S. Main St. (100) 3034	Winchester--S. Main St. (100) 3034 Rem 3ph riser, cable, & xfmr bank in vault AP2-YWO Total Cost Variance Met - Variance :14.143 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2L720400	New Hartford--Steele Rd. (120) 1189	New Hartford--Steele Rd. (120) 1189 Repl pole & inst new oh/ug svc. Rem extg AP2-YWO Total Cost Variance Met - Variance :-13.9725 MIN.:-40 MAX.:40	Salvage -M02	108040	1
2L720526	THOMASTON - WATERTOWN AVE SUNOCO -	THOMASTON - WATERTOWN AVE SUNOCO - CHANGING SVC FROM OH TO DB AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2L720577	Canton--Gracy Rd. (180) 2061 Fronti	Canton--Gracy Rd. (180) 2061 Frontier to repl pole. Shft & inst 4/0 oh/ug svc AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2L720624	Torrington--Lincoln Ave. 1114S Repl	Torrington--Lincoln Ave. 1114S Repl & relocate stub pole AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2L720630	BURLINGTON-MILFORD ST / PRIORITY RE	BURLINGTON-MILFORD ST / PRIORITY REJECT POLE- REPLACE AND SHIFT AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2L720762	TORRINGTON - FRANKLIN ST / ADD LIGH	TORRINGTON - FRANKLIN ST / ADD LIGHTS BEHIND SLOVAK CLUB AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2L720851	WATERTOWN - BUCKINGHAM / REPLACE RE	WATERTOWN - BUCKINGHAM / REPLACE RECLOSER AND CONTROL - YELLOW TAG DC-YWO Variance - Design/Construction	Salvage -M02	108040	1
2L720985	Elec Maint Pole Reject - PRIORITY D	Elec Maint Pole Reject - PRIORITY DESG (IFOH) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2L820645	SW CDOT 05-114 RT 219/318 ROAD IMPR	SW CDOT 05-114 RT 219/318 ROAD IMPROVEMENTS BARKHAMSTED JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2L920208	AN - 2019 DEF POLES POLE# 103 SUNSE	AN - 2019 DEF POLES POLE# 103 SUNSET HILL RD NORFOLK CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
2M031644	CDOT 166-103 - Wolcott Rd (RTE 69)	CDOT 166-103 - Wolcott Rd (RTE 69) Bridge Replacement - Relocate Pole Line-Temp JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2M220215	103626-01 W Main Street 3A New Bri	103626-01 W Main Street 3A New Britain Secondary Replacement CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
2M322576	Elec Proj Highway Relocation Reimbu	Elec Proj Highway Relocation Reimbursable Specific DESG (MIBPROJ) JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2M322577	CDOT 17-186 - RTE 6 Bristol Road Wi	CDOT 17-186 - RTE 6 Bristol Road Widening - OH 3 of 6 - Poles 15691 to 15809(TR) JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2M322578	CDOT 17-186 - RTE 6 Bristol Road Wi	CDOT 17-186 - RTE 6 Bristol Road Widening - OH 4 of 6 - Poles 15827 to Camp St JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2M322581	CDOT 17-186 - RTE 6 Bristol Road Wi	CDOT 17-186 - RTE 6 Bristol Road Widening - UG Secondary SVC JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2M421934	Jpt-Granger Rd Brstl P7085 & P6746	Jpt-Granger Rd Brstl P7085 & P6746 - Rplc Poles Shift 1PH Primary	Salvage -M02	108040	1
2M422728	Jpt-298 South St Brstl P2901-S - 9a	Jpt-298 South St Brstl P2901-S - 9a - Rplc Pole/Span & SW Guy in concrete AP2-YWO Total Cost Variance Met - Variance :68.3096 MIN.:-50 MAX.:150	Salvage -M02	108040	1
2M423451	RTM-93 Cherry Hill Rd, Nwt. Remove	RTM-93 Cherry Hill Rd, Nwt. Remove OH Ariel Trespass Over Driveway Feeding #99	Salvage -M02	108030	1
2M423467	CDOT 17-186 - RTE 6 Bristol Road Wi	CDOT 17-186 - RTE 6 Bristol Road Widening - OH 2 of 6 - Pole 2299 to Pole 15691 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2M520845	CDOT 17-186 - RTE 6 Bristol Road Wi	CDOT 17-186 - RTE 6 Bristol Road Widening - Additional Pole Relocations JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2M521161	CDOT 17-186 - CD00045 - Temporary L	CDOT 17-186 - CD00045 - Temporary Line Relocation, RTE 6 near Stafford Ave JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2M521942	RTM-788 Old Turnpike Rd, SOG. AT&T	RTM-788 Old Turnpike Rd, SOG. AT&T Pole Rejects. Replace P#54 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M522454	CDOT 110-132 Allentown Rd reconstru	CDOT 110-132 Allentown Rd reconstruction, Plymouth AP2-YWO Total Cost Variance Met - Variance :-26.3616 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M522895	CD00323-01 Elm St Secondary Recondu	CD00323-01 Elm St Secondary Reconductoring AP2-YWO Total Cost Variance Met - Variance :13.8355 MIN.:-20 MAX.:20	Salvage -M02	108040	1
2M522896	CD00323-01 Chestnut St Secondary Re	CD00323-01 Chestnut St Secondary Reconductoring CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
2M620312	RTM-371 S Curtis St, Mer. Frontier	RTM-371 S Curtis St, Mer. Frontier Pole Reject. P#1610 AP2-YWO Total Cost Variance Met - Variance :2.6562 MIN.:-50 MAX.:50	Salvage -M02	108040	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
2M620318	RTM-101 Warren St, Mer. Frontier Po	RTM-101 Warren St, Mer. Frontier Pole Reject. P#4730 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M620326	WC/JJH-49 Depaolo Dr, Southington.	WC/JJH-49 Depaolo Dr, Southington. CO-GEN INTERCONNECT CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
2M620842	DM 1483 Cheshire St CHES Change ove	DM 1483 Cheshire St CHES Change over FTR P#3731 CONV#380812 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M621311	(DF) (R/I) PTT Light pole 1586 - -6	(DF) (R/I) PTT Light pole 1586 - -6/11 ESO 9A - Car v light pole- COMP 12/28 CCC CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
2M621361	PN 492601 13F63 CDOT 151-273- RELOC	PN 492601 13F63 CDOT 151-273- RELOCATE TEMP OH LINE-SEG 4 - OOS#5 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2M621532	Jpt-32 Sandra Ave Plymth P2625 - 9a	Jpt-32 Sandra Ave Plymth P2625 - 9a - Shift Open Wire DE Sec. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M621550	RTM-Lot 930 Division St, Ber. New C	RTM-Lot 930 Division St, Ber. New Commercial 3PH OH Temp 200A 120/208 M/L-C AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M621645	WC-Norton St Sog 9A car vs pole 881	WC-Norton St Sog 9A car vs pole 88159 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M621676	Jpt-ESO-24 Matthews St Brstl P248 -	Jpt-ESO-24 Matthews St Brstl P248 - 9a - Shift 3PH Facilities Rplc 25 Kva AP2-YWO Total Cost Variance Met - Variance :101.535 MIN.:-50 MAX.:150	Salvage -M02	108040	1
2M621693	(DF)(R/I)Spcr Tang w/Answay- Guy- 1	(DF)(R/I)Spcr Tang w/Answay- Guy- 1 Ph Tap, Shift Facilities-DESG conv# 393900 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M621699	(DF) FTR8658-35-40',(R/I)Spacer Sma	(DF) FTR8658-35-40',(R/I)Spacer Small, Guy, Shift Wires- conv# 393950 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M621782	PT Convo #402122-MakeReadyWirelessA	PT Convo #402122-MakeReadyWirelessAttachReimb-Frontier-Parent Convo # 397483 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M621783	PT Convo# 402134-MakeReadyWirelessA	PT Convo# 402134-MakeReadyWirelessAttachReimb-Frontier-Parent Convo# 397492 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M621859	(CH) P#'S 948 & 5947: SHFT PRIORITY	(CH) P#'S 948 & 5947: SHFT PRIORITY POLES_WATERBURY_MIB PROJECT AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M621871	REPLACE YELLOW TAGGED RECLOSER (Y-1	REPLACE YELLOW TAGGED RECLOSER (Y-17764-2016) 12B33-91T POLE C2225 AP2-YWO Total Cost Variance Met - Variance :21.4876 MIN.:-40 MAX.:40	Salvage -M02	108040	1
2M621872	EJC 721 Russell Rd Wethersfield P#3	EJC 721 Russell Rd Wethersfield P#316 Ftr Replaced Pole, Shifted Facilities AP3-YWO Resource Variance Met- Labor 29 <= 32 OR 150.52 <= 30 And Contractor $0 <= 2000	Salvage -M02	108040	1
2M621899	(DF) Ple 9634-(R/I) 2 ph Tang w dn	(DF) Ple 9634-(R/I) 2 ph Tang w dn guy- DESG (MIBPROJ) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M621929	AMM WARREN ST,WATERBURY. SHIFT FRO	AMM WARREN ST,WATERBURY. SHIFT FRONTIER POLE 8795 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M622249	EJC 718 West Main St, Waterbury P#1	EJC 718 West Main St, Waterbury P#121 Repl Alum Stlt Pole and Heads AP2-YWO Total Cost Variance Met - Variance :-11.0863 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M622292	WC-39 Luke St,Propsect. Car v Pole	WC-39 Luke St,Propsect. Car v Pole 2507 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M622446	JC/35 OLD FAIRWOOD RD. BETHANY/ REM	JC/35 OLD FAIRWOOD RD. BETHANY/ REM BACK YARD SVC./SEC. MOVE TO ROAD NEW POLE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M622538	JC/Elec Maint Trouble Call - Proper	JC/Elec Maint Trouble Call - Property Damage OH (INSOH) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M622617	EJC 1897 Stanley St, NB P#103 Ftr R	EJC 1897 Stanley St, NB P#103 Ftr Replaced Pole, Shifted Facilities, POST CONSTR AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M622666	Jpt-777 Wolcott St Wtby (Frnt)P7539	Jpt-777 Wolcott St Wtby (Frnt)P7539-S - 9a - Rplc'd 2 Stubs Shifted Svc Riser AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M622771	JC/39 FENN RD MIDDLEBURY / POLE 174	JC/39 FENN RD MIDDLEBURY / POLE 1747 SHIFT GUY ONLY(ALL OTHER WORK COMP) CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
2M622924	Waterbury Rd Prospect 9A - (POST CO	Waterbury Rd Prospect 9A - (POST CONSTRUCTION) AP2-YWO Total Cost Variance Met - Variance :-26.9179 MIN.:-40 MAX.:40	Salvage -M02	108040	1
2M622949	Jpt-ESO-5 Paul St Plnv P3110 & P125	Jpt-ESO-5 Paul St Plnv P3110 & P12539 - Rplc Poles Shift 1PH Delta DE Xarm AP2-YWO Total Cost Variance Met - Variance :3.4593 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M623032	(DF) sog, Replace stub Ple81031-S,	(DF) sog, Replace stub Ple81031-S, guying & Anc - Property Damage OH (INSOH)-9A AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M623045	RTM-Meetinghouse Village Meriden 6	RTM-Meetinghouse Village Meriden 6 Locations - COMPLETED 1/19/17 CCC CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
2M623051	WC/ESO -11/17 Union ST/ Brass Mill	WC/ESO -11/17 Union ST/ Brass Mill Rd Wtby 9A- POLE # 3308-9 & BASE AP2-YWO Total Cost Variance Met - Variance :-48.4881 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M623162	RTM-Municipal Light Fault Locate an	RTM-Municipal Light Fault Locate and Repair@ POLE 1 - COMP 12/21 ASP AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M720275	WC-1/22 ESO/AWC 48 TODD RD WOLCOTT	WC-1/22 ESO/AWC 48 TODD RD WOLCOTT Car vs pole # 1864 CASE# 2017-601 AP2-YWO Total Cost Variance Met - Variance :9.7651 MIN.:-30 MAX.:30	Salvage -M02	108040	1
2M720276	WC-1523 Farmington Ave, Farmington.	WC-1523 Farmington Ave, Farmington. Car vs pole 109S AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M720318	EJC Deming St, Newington P#914 Cut&	EJC Deming St, Newington P#914 Cut&Kick, Shift Facilities AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M720353	JC/Municipal Light Fault Locate and	JC/Municipal Light Fault Locate and Repair@ POLE L1-P130 - COMP 4/3 CCC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M720395	(DF) Prospect- Ple 94 Change cutout	(DF) Prospect- Ple 94 Change cutouts, TERRY Rd PROSPECT AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M720502	EC 11H65 REHAB - Plainville	EC 11H65 REHAB - Plainville CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
2M720552	Municipal Light Fault Locate and Re	Municipal Light Fault Locate and Repair@ POLE 4 - COMP 4/11 CCC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M720579	WC-ESO 12/24 LONG HILL RD WATEBURY	WC-ESO 12/24 LONG HILL RD WATEBURY - POLE # 6550- 9A AP3-YWO Resource Variance Met- Labor 0 <= 32 OR -100 <= 30 And Contractor $1630.79 <= 2000	Salvage -M02	108040	1
2M720580	RTM-839 Murdock Ave, Mer. Existing	RTM-839 Murdock Ave, Mer. Existing Res Upgrade. Replace & Relocate OH Svc. M/L-C	Salvage -M02	108040	1
2M720587	WC/1/14 - ESO 115 Windy Dr Wtby 9A	WC/1/14 - ESO 115 Windy Dr Wtby 9A CAR VS POLE # 9781 AP2-YWO Total Cost Variance Met - Variance :9.6092 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M720591	WC-1/14 - ESO - 1280 MARION RD CHES	WC-1/14 - ESO - 1280 MARION RD CHESHIRE P# 815 HIT ON 1/8 CASE # 2017-495 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M720601	WC-1/2 - ESO 233 Matthews St Bristo	WC-1/2 - ESO 233 Matthews St Bristol CAR VS POLE # 3674 CASE # 17-00090 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M720625	DM 1145 CHESHIRE ST CHESHIRE 9A P#2	DM 1145 CHESHIRE ST CHESHIRE 9A P#2009 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M720697	RTM-220 Coe Ave, Mer. Relocate Pole	RTM-220 Coe Ave, Mer. Relocate Poles for new Enterance 100% Chargeable MS-YWO Variance - Multiple Setups	Salvage -M02	108040	1
2M720734	*EMERGENCY* SHIFT TO FRONTIER DBL P	*EMERGENCY* SHIFT TO FRONTIER DBL POLE 10093 - Property Damage OH (INSOH) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M720747	WC-87 S Main St,Naugatuck. Car v Po	WC-87 S Main St,Naugatuck. Car v Pole 1634 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M720798	WC-498 Pine St, Wtrbry. Ca v pole 2	WC-498 Pine St, Wtrbry. Ca v pole 29468 .Set new pole and new xfmr AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M720799	JPT Tomlinson Ave Plainville Shelte	JPT Tomlinson Ave Plainville Sheltered Ponds Cono'P#14682 needs replacement AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M720850	STRAITSVILLE RD, PROSPECT. POLES 42	STRAITSVILLE RD, PROSPECT. POLES 42 & 44 AP3-YWO Resource Variance Met- Labor 47 <= 32 OR -97.92 <= 30 And Contractor $0 <= 2000	Salvage -M02	108040	1
2M720867	RTM-SMITHFIELD AVE, MERIDEN. POLE 8	RTM-SMITHFIELD AVE, MERIDEN. POLE 80551 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M720868	DM MILLER RD, BETHANY. POLE 1820	DM MILLER RD, BETHANY. POLE 1820 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M720946	600 STRAITS TPK WTN./ REPLACE POLE&	600 STRAITS TPK WTN./ REPLACE POLE& RISER CUT KICK AP2-YWO Total Cost Variance Met - Variance :46.7562 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M720949	RTM-220 Berlin Tpke, Ber. Relocate	RTM-220 Berlin Tpke, Ber. Relocate P#99264 & P#4728 100% Reimbursable AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721032	(DF) drhm(I) 277/480 Padmount XF &	(DF) drhm(I) 277/480 Padmount XF & 400A DB svc -- New Com/Ind DESG (DN) AP2-YWO Total Cost Variance Met - Variance :1.0538 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M721033	PT Conv# 493259-MakeReadyNonReimb-F	PT Conv# 493259-MakeReadyNonReimb-Fibertech-ParentConv# 490746 AP2-YWO Total Cost Variance Met - Variance :-28.8835 MIN.:-50 MAX.:50	Salvage -M02	108040	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
2M721080	WC-2/18/17 ESO 46 ROUND HILL RD BRI	WC-2/18/17 ESO 46 ROUND HILL RD BRISTOL CAR VS POLE # 6728 CASE # 17-6122 AP2-YWO Total Cost Variance Met - Variance :4.5771 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M721152	WC-2/25/17 ESO 221 DIANA RD SOUTHIN	WC-2/25/17 ESO 221 DIANA RD SOUTHINGTON CAR VS POLE # 2009 & 2010 AP2-YWO Total Cost Variance Met - Variance :7.5386 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M721153	CAR VS SVC; RPL TPX SVC TO COMM REP	CAR VS SVC; RPL TPX SVC TO COMM REPAIR/UPGRADE FROM POLE 61693 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721164	WC-2/25/17 ESO 267 SANDY HILL RD MI	WC-2/25/17 ESO 267 SANDY HILL RD MIDDLEBURY CAR VS POLE # F5107 AP2-YWO Total Cost Variance Met - Variance :19.5987 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M721176	Jpt-Washington St Plnv (Frnt)P288 -	Jpt-Washington St Plnv (Frnt)P288 - Shift 3PH Facilities AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721206	AMM 788 FARMINGTON AVE,FARMINGTON.	AMM 788 FARMINGTON AVE,FARMINGTON. INSTALL NEW 3PH DB SERVICE. AP3-YWO Resource Variance Met- Labor 4 <= 32 OR 8.38 <= 30 And Contractor $0 <= 2000	Salvage -M02	108040	1
2M721272	RTM-46 Norris St, Wtby. Frontier Po	RTM-46 Norris St, Wtby. Frontier Pole Reject P#62-1/2 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721289	AMM 15 WHITEHALL PL, FARMINGTON. D	AMM 15 WHITEHALL PL, FARMINGTON. DB SECONDARY CABLE FAULT. MADE REPAIRS. CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
2M721364	RTM-216 Percival Ave, Ber. ESO-9A-C	RTM-216 Percival Ave, Ber. ESO-9A-Car vs P#8431 POST CONSTRUCTION AP2-YWO Total Cost Variance Met - Variance :54.3288 MIN.:-50 MAX.:150	Salvage -M02	108040	1
2M721388	PT Conv# 498791-MakeReadyNonReimb-F	PT Conv# 498791-MakeReadyNonReimb-Fibertech-ParentConv# 497106 AP2-YWO Total Cost Variance Met - Variance :-34.289 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M721441	3/25/17 ESO 657 WATERTOWN AVE CAR V	3/25/17 ESO 657 WATERTOWN AVE CAR VS POLE#7269 CASE#17-25314 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721499	Jpt-Riverside Ave BRI P10581 - 9a -	Jpt-Riverside Ave BRI P10581 - 9a - Rplc'd 35Ft/C-2 Shifted Sec. & Svc AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721549	DM ESO 3/29/17 9A WOLF HILL RD WOL	DM ESO 3/29/17 9A WOLF HILL RD WOLCOTT car vs frontier P# 4604 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721584	Jpt-5 Two Mile Rd Farm (Frnt)P38 -	Jpt-5 Two Mile Rd Farm (Frnt)P38 - Line Relocation Reimbursable AP3-YWO Resource Variance Met- Labor 15 <= 32 OR 38.61 <= 30 And Contractor $0 <= 2000	Salvage -M02	108040	1
2M721616	ESO 4/2/17 9A - 92 PARK RD WATERBUR	ESO 4/2/17 9A - 92 PARK RD WATERBURY CAR VS POLE # 1453 CASE# 17-27626 AP2-YWO Total Cost Variance Met - Variance :-47.3901 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M721634	AMM 75 RESERVOIR RD FARMINGTON. RE	AMM 75 RESERVOIR RD FARMINGTON. REPLACE DB SERVICE & RISER. AP2-YWO Total Cost Variance Met - Variance :-44.6321 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M721636	Jpt-Terryville Ave BRI (Frnt)P6309	Jpt-Terryville Ave BRI (Frnt)P6309 - 9a - DUMP TRUCK BROUGHT POLE & WIRE DOWN AP2-YWO Total Cost Variance Met - Variance :29.3622 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M721686	EJC 370 New Britain Ave, Newington	EJC 370 New Britain Ave, Newington P#4835 FTR Replaced Pole, Shift Facilities AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721691	(DF) Drhm, (R/I) DB 2ndry & HH- & s	(DF) Drhm, (R/I) DB 2ndry & HH- & svc - Elec Svc Existing Residential DESG (DN) CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
2M721694	RTM-Willow Brook Ball Park. 9A-Tran	RTM-Willow Brook Ball Park. 9A-Transformer Fire. Replaced 500KVA 277/480 AP3-YWO Resource Variance Met- Labor 3 <= 32 OR 3.36 <= 30 And Contractor $0 <= 2000	Salvage -M02	108040	1
2M721697	PT Conv# 505840-MakeReadyNonReimb-V	PT Conv# 505840-MakeReadyNonReimb-VerizonWireless-ParentConv# 500248 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721712	WC-420 N Main ST,Sog. Upgrade svc t	WC-420 N Main ST,Sog. Upgrade svc to 3ph 480/277. M/L coordinate AP2-YWO Total Cost Variance Met - Variance :43.8246 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M721752	RTM-9 Glen Hills Rd, Mer. 9A-ESO-Ca	RTM-9 Glen Hills Rd, Mer. 9A-ESO-Car vs P#100 CASE#17-2559 AP2-YWO Total Cost Variance Met - Variance :-17.6764 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M721758	DM 64 Wolcott RD WOLCOTT P#2211 out	DM 64 Wolcott RD WOLCOTT P#2211 outage to remove vines growing in livefront xfmr AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721761	AMM 1305 FARMINGTON AVE, FARM. 9A C	AMM 1305 FARMINGTON AVE, FARM. 9A CAR VS POLE. SHIFT TO NEW FRONTIER POLE 76. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721806	AMM RED OAK HILL RD,FARMINGTON. SH	AMM RED OAK HILL RD,FARMINGTON. SHIFT FRONTIER POLE 360. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721811	WC-504 BURRITT ST, SOUTHINGTON - RE	WC-504 BURRITT ST, SOUTHINGTON - RELOCATE SVC RISER FROM P4350 TO P 5111 CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
2M721829	DM 5/18 E MITCHELL AVE CHESHIRE - D	DM 5/18 E MITCHELL AVE CHESHIRE - DB FAULT Replace Cable VLT#B to PAD#C AP2-YWO Total Cost Variance Met - Variance :15.3973 MIN.:-40 MAX.:40	Salvage -M02	108040	1
2M721858	Jpt-72 Colony St BRI (Frnt)P4320 -	Jpt-72 Colony St BRI (Frnt)P4320 - Existing Residential Overhead - MLC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721891	EJC 281 Brittany Farms Rd, NB P#3 P	EJC 281 Brittany Farms Rd, NB P#3 PTT Pole/Head Needs Replacing- COMP 8/5 CCC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721926	AMM 47 BURNT HILL RD FARMINGTON. R	AMM 47 BURNT HILL RD FARMINGTON. REPLACE DB STREETLIGHT HEAD. POLE 2502. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721945	ESO/AWC 5/26 WATERBURY, MERIDEN RD	ESO/AWC 5/26 WATERBURY, MERIDEN RD - 9A P 9259 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M721951	EJC 116 South Mountain Dr, New Brit	EJC 116 South Mountain Dr, New Britain P#98992 Repl Svc to Midspan per T-Ticket AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722022	DM 6/5 CHESHIRE, 214 ACADEMY RD - 9	DM 6/5 CHESHIRE, 214 ACADEMY RD - 9A P4867 - AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722045	JC/200 PARK RD. NAUG Electric Serv	JC/200 PARK RD. NAUG Electric Service Existing Residential Overhead AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722088	Municipal Light Fault Locate and Re	Municipal Light Fault Locate and Repair@ POLE 3 - COMP 7-6-17 CCC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722094	Municipal Light Fault Locate and Re	Municipal Light Fault Locate and Repair@ POLE 248 - COMP 6/20 CCC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722117	Jpt-ESO- Hart Pl Plnv P99400 - Rplc	Jpt-ESO- Hart Pl Plnv P99400 - Rplc Rotted Secondary Pole CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
2M722145	EJC 40 Cedar St, Newington P#445 FT	EJC 40 Cedar St, Newington P#445 FTR to Replace Pole, Shift Facilities AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722157	Municipal Light Fault Locate and Re	Municipal Light Fault Locate and Repair @ POLE 2561 - COMP 6/22 CCC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722162	Municipal Light Fault Locate and Re	Municipal Light Fault Locate and Repair@ POLE 3758 - COMP 6/17 CCC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722167	RTM-315 Bee St, Mer. 9A-ESO-Car vs	RTM-315 Bee St, Mer. 9A-ESO-Car vs P#2192. Pole Replaced. Post Construction AP2-YWO Total Cost Variance Met - Variance :-13.7915 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M722169	RTM-437 West Ln, Ber. 9A-ESO Car vs	RTM-437 West Ln, Ber. 9A-ESO Car vs P#5485. Pole Replaced POST CONSTRUCTION AP2-YWO Total Cost Variance Met - Variance :12.5508 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M722186	JC/47 RED ROBIN RD NAUG- NEED NEW	JC/47 RED ROBIN RD NAUG- NEED NEW HH & 4 POS.CONNECTORS AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722207	WC-6/19 SOUTHINGTON, CLARK ST - 9A	WC-6/19 SOUTHINGTON, CLARK ST - 9A P3900 -REPLCD POLE, ARMS, CUTOUTS AP2-YWO Total Cost Variance Met - Variance :94.7582 MIN.:-50 MAX.:150	Salvage -M02	108040	1
2M722211	EJC Webster Ct, Newington Replace P	EJC Webster Ct, Newington Replace PTT Poles Damaged by Landscaping Contractor AP2-YWO Total Cost Variance Met - Variance :-24.1926 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M722247	DM 35 Niagara St WTBY P#6803 Change	DM 35 Niagara St WTBY P#6803 Change Recloser & Control 13F68-70S AP2-YWO Total Cost Variance Met - Variance :8.9673 MIN.:-40 MAX.:40	Salvage -M02	108040	1
2M722269	Municipal Light Fault Locate and Re	Municipal Light Fault Locate and Repair@ POLE 4150 - COMP 7-8-17 CCC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722310	Municipal Light Fault Locate and Re	Municipal Light Fault Locate and Repair@ POLE L1-654 Replaced 140ft of #4 CBL. CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
2M722316	Jpt-Milton Rd BRI P9340 - Rplc'd ro	Jpt-Milton Rd BRI P9340 - Rplc'd rotted xarm with Ridge Pin Const. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722328	ESO 5/21/17 - WOLCOTT - 27 COUNTY R	ESO 5/21/17 - WOLCOTT - 27 COUNTY RD P# 2312 - no addtl info to date 6/28 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722333	AMM 268 N MAIN ST , WATERBURY. REP	AMM 268 N MAIN ST , WATERBURY. REPLACE BROKEN HANDHOLE. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722338	AMM 155 SONGBIRD LN,FARM. DB PRIMAR	AMM 155 SONGBIRD LN,FARM. DB PRIMARY CABLE FAULT. MADE REPAIRS. AP2-YWO Total Cost Variance Met - Variance :-39.9293 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M722403	JC/Deerfield Ln Bethany Animal Prot	JC/Deerfield Ln Bethany Animal Protection AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722406	JC/Crestwood Dr Naug Fuse 5255 Anim	JC/Crestwood Dr Naug Fuse 5255 Animal Protection AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722408	WC 7/6 SOUTHINGTON, MINE HOLLOW RD/	WC 7/6 SOUTHINGTON, MINE HOLLOW RD/LONG BOTTOM - 9A P93393 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
2M722436	RSO/AWC 7/10 CHESHIRE, W JOHNSON AV	RSO/AWC 7/10 CHESHIRE, W JOHNSON AVE - RECONDUCTERING 250' CONDUIT/CABLE CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
2M722455	WC 7/11 SOUTHINGTON, MAIN ST - REPL	WC 7/11 SOUTHINGTON, MAIN ST - REPLACED 3 PH BANK & 2 CUTOUTS P86145 AP2-YWO Total Cost Variance Met - Variance :20.4912 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M722543	Jpt-RSO- Middle St BRI P6285 - 9a -	Jpt-RSO- Middle St BRI P6285 - 9a - Replaced pole Shifted 3PH Tan & 3PH Tap CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
2M722553	Greystone Rd,Wtby. Make upgrades on	Greystone Rd,Wtby. Make upgrades on 64496,64497,G413&64500 for animal protection AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722576	DM RSO 7/19 CREAMERY RD, DURHAM - B	DM RSO 7/19 CREAMERY RD, DURHAM - BROKEN P 1092 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722592	AMM 65 BENEDICT ST,WTBY. REPLACED	AMM 65 BENEDICT ST,WTBY. REPLACED XFMR BANK. REPLACED 3 CUTOUTS. CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
2M722602	WC-RSO 7/21 SOUTHINGTON, WEST ST -	WC-RSO 7/21 SOUTHINGTON, WEST ST - 9A P92660 PICK UP SNAGGED WIRE - REPLD SVC	Salvage -M02	108040	1
2M722664	JC/RSO 7/22 NAUGATUCK, NEW HAVEN RD	JC/RSO 7/22 NAUGATUCK, NEW HAVEN RD- 9A P3602 - BROKEN POLE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722719	JC/RSO 7/28 MIDDLEBURY, SOUTH ST -	JC/RSO 7/28 MIDDLEBURY, SOUTH ST - TRUCK TOOK DOWN SVC - RAN 130' #2 SVC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722757	RSO NEW BRITAIN, Biruta St - Replac	RSO NEW BRITAIN, Biruta St - Replace 50' #2 OH Service @ P53400 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722797	AMM 455 CHASE PKWY,WTBY. PART POWER	AMM 455 CHASE PKWY,WTBY. PART POWER. REPAIRED PRIMARY CABLE NEAR POLE F8074. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722833	Jpt-RSO- Park Hill Rd BRI - Rplc'd	Jpt-RSO- Park Hill Rd BRI - Rplc'd 4 (Frnt) Poles & 1 Xfrm AP2-YWO Total Cost Variance Met - Variance :104.2948 MIN.:-50 MAX.:150	Salvage -M02	108040	1
2M722839	RSO SOUTHINGTON, Belleview Ave - I	RSO SOUTHINGTON, Belleview Ave - Installed 15 KV arrestor at Pad A CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
2M722853	AMM 32 DEPOT PL, FARMINGTON. REPLA	AMM 32 DEPOT PL, FARMINGTON. REPLACED 3 PH BANK ON POLE 2350 & ADDED 3 CUTOUTS. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722861	WC-8/10 SOUTHINGTON, BRISTOL ST - 9	WC-8/10 SOUTHINGTON, BRISTOL ST - 9A P 2647 - CAR V POLE & 3 PH BANK XFRMS AP2-YWO Total Cost Variance Met - Variance :-4.2993 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M722889	DM/RSO 8/13 WOLCOTT, LONG SWAMP RD-	DM/RSO 8/13 WOLCOTT, LONG SWAMP RD- 9A P 5000 - LONGO/KENNEY AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722892	CD00927 - CDOT 151-326 - I84 Mix Ma	CD00927 - CDOT 151-326 - I84 Mix Master Rehab - Remove Streetlights &Secondaries JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2M722893	CD00927 - CDOT 151-326 - I84 Mix Ma	CD00927 - CDOT 151-326 - I84 Mix Master Rehab - Extend MH's to New Street Level JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2M722903	ESO 9A 6/8 WATERBURY, 593 SYLVAN AV	ESO 9A 6/8 WATERBURY, 593 SYLVAN AVE - 9A P7260 - AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M722919	RTM-1821 N Broad St, Mer. 9A Car vs	RTM-1821 N Broad St, Mer. 9A Car vs P#3141. Frontier Replaced. POST CONSTRUCTION AP2-YWO Total Cost Variance Met - Variance :-29.3137 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2M722933	DM/ESO 9A 6/10/17 - CHESHIRE - P#85	DM/ESO 9A 6/10/17 - CHESHIRE - P#853 RESAG OH SVC 1308 S MERIDEN RD AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M723013	Jpt-RSO-518 Jerome Ave BRI P2073 -	Jpt-RSO-518 Jerome Ave BRI P2073 - RAN NEW 100' #2 SVS MIDSPANNED AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M723018	EJC 66 Clifford St, Newington P#602	EJC 66 Clifford St, Newington P#6022 Replaced Pole, Xfrmr, Shift Facilities AP2-YWO Total Cost Variance Met - Variance :134.8751 MIN.:-50 MAX.:150	Salvage -M02	108040	1
2M723162	WC-9/3 RSO P#1468 INSTLLD, CO NEED	WC-9/3 RSO P#1468 INSTLLD, CO NEED RHANG TPX TO NEW POLE + HANG SRV TO HOUSE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M723627	Jpt-Lexington Ave Wtby P62509 - Rpl	Jpt-Lexington Ave Wtby P62509 - Rplc'd Pole - PER KEN GROHS - XFMR WAS NOT REPL CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
2M724513	Jpt-7 Pickett Ln Farm (Frnt)P6024 -	Jpt-7 Pickett Ln Farm (Frnt)P6024 - Existing Residential Overhead - MLC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M820194	AMM 12 GILLETTE WAY FARM. Municipa	AMM 12 GILLETTE WAY FARM. Municipal Light Fault Locate and Repair@ POLE 2926. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M820195	AMM 12 GILLETTE WAY,FARM. Municipa	AMM 12 GILLETTE WAY,FARM. Municipal Light Fault Locate and Repair@ POLE 2927. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M820295	Jpt-RSO-320 Farmington Ave Plnv P15	Jpt-RSO-320 Farmington Ave Plnv P1515 - REPL 1000 WATT BULB AND EYE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M821305	CDOT 17-186 - RTE 6 Bristol Road Wi	CDOT 17-186 - RTE 6 Bristol Road Widening - Additional Pole Sets to New Depth JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2M821520	AMM 25 HATTERS LN,FARM. REPLACE &	AMM 25 HATTERS LN,FARM. REPLACE & RELOCATE OH SERVICE TO NEW ATTACHMENT POINT. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M923592	RTM-Yale Acres, Meriden. OH/DB Conv	RTM-Yale Acres, Meriden. OH/DB Conversion. Phase 1 of 6 (C-01) CD00551-02 AP2-YWO Total Cost Variance Met - Variance :-3.9788 MIN.:-40 MAX.:40	Salvage -M02	108040	1
2M923734	RTM-1 Washington Hts, Mer. Existing	RTM-1 Washington Hts, Mer. Existing Res Upgrade. Replace OH Svc. M/L-C 200A 1PH AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2M924043	EJC 62 New Britain Rd, Berlin Repl	EJC 62 New Britain Rd, Berlin Repl 3ph Bank, Inst OH/DB Svc to Pedestal, M/L/C	Salvage -M02	108040	1
2W421201	PHD BM/ Pole 1342 Install 600 Amp s	PHD BM/ Pole 1342 Install 600 Amp switches CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
2W421609	JAM CHANGE OUT SW GEAR AND CABLE FA	JAM CHANGE OUT SW GEAR AND CABLE FAULT	Salvage -M02	108030	1
2W421636	JD 492601 13F64 RELOCATE OH LINE CD	JD 492601 13F64 RELOCATE OH LINE CDOT 151-273- SEG 2 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2W421645	JD 492601 13F64 REMOVE/RELOCATE OH	JD 492601 13F64 REMOVE/RELOCATE OH LINE-CDOT 151-273 - SEG 2 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
2W520098	ROTTED FRNTR POLE #8951 INSTALLED R	ROTTED FRNTR POLE #8951 INSTALLED RIDGE PIN NEUTRAL CLAMP & SHIFTED	Salvage -M02	108040	1
2W521082	VT/RUN NEW OH SVC - TAKEN OUT BY S	VT/RUN NEW OH SVC - TAKEN OUT BY STORM - NEW MAST INSTALLED AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2W521224	ESO 7/12 COOKE ST, WATERBURY - CAR	ESO 7/12 COOKE ST, WATERBURY - CAR VS P# 14126	Salvage -M02	108040	1
2W521547	Lantern Park Dr., Naugatuck - Cable	Lantern Park Dr., Naugatuck - Cable Replacement	Salvage -M02	108040	1
2W522049	PHD Elec Maint Replace/Renewal/Obs	PHD Elec Maint Replace/Renewal/Obsol OH DESG (AROH) AP2-YWO Total Cost Variance Met - Variance :112.0869 MIN.:-50 MAX.:150	Salvage -M02	108040	1
2W522136	PHD VT *REJECT POLES* - SHIFT AF	PHD VT *REJECT POLES* - SHIFT AFTER FRONTIER SETS POLES AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2W522187	PHD Elec Maint Replace/Renewal/Ob	PHD Elec Maint Replace/Renewal/Obsol OH DESG (AROH) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2W522237	PHD JAM Frontier reject poles nee	PHD JAM Frontier reject poles need to be changed over AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2W620005	PHD Elec Maint Replace/Renewal/Ob	PHD Elec Maint Replace/Renewal/Obsol OH DESG (AROH) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2W620038	PHD Elec Maint Replace/Renewal/Obs	PHD Elec Maint Replace/Renewal/Obsol OH DESG (AROH) CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
2W620080	PHD Elec Maint Replace/Renewal/Ob	PHD Elec Maint Replace/Renewal/Obsol OH DESG (AROH) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2W620099	PHD Elec Maint Replace/Renewal/Obs	PHD Elec Maint Replace/Renewal/Obsol OH DESG (AROH) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2W620198	PHD Elec Maint Replace/Renewal/Ob	PHD Elec Maint Replace/Renewal/Obsol OH DESG (AROH) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2W620247	PHD JC/ POLE 9436 FRONTIER SHIFT	PHD JC/ POLE 9436 FRONTIER SHIFT AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2W620270	PHD JC/ POLE 8971 FRONTIER SHIFT	PHD JC/ POLE 8971 FRONTIER SHIFT AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2W620297	PHD Elec Maint Replace/Renewal/Ob	PHD Elec Maint Replace/Renewal/Obsol OH DESG (AROH) P# 6615 AP2-YWO Total Cost Variance Met - Variance :47.7694 MIN.:-50 MAX.:50	Salvage -M02	108040	1
2W620324	VT/REMOVE EXISTING LIGHT...INSTALL	VT/REMOVE EXISTING LIGHT...INSTALL 100W LED COBRA HEAD ON 12' BRACKET	Salvage -M02	108040	1
2W620538	Proj#CD00699-13B33 Relocate for Tra	Proj#CD00699-13B33 Relocate for Trans, Part 3 of 6: Chase Pkwy w/ 556 CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
2W620715	CAR VS FRONTIER POLE #35 POLE IS CR	CAR VS FRONTIER POLE #35 POLE IS CRACKED & ROTTED SHOULD BE REPLACED AP2-YWO Total Cost Variance Met - Variance :66.1647 MIN.:-50 MAX.:150	Salvage -M02	108040	1
2W620798	DM 5/3 ESO CAR VS POLE WATERBURY RD	DM 5/3 ESO CAR VS POLE WATERBURY RD PRSPCT P#1366 CONV#393701 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2W620826	JDB 54 PORTER HILL RD MIDDLEBURY R	JDB 54 PORTER HILL RD MIDDLEBURY REPLACE POLE 61480 & SHIFT CONV#449244 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2W620862	VT/WC-27 Williams Dr, Prospect. SHI	VT/WC-27 Williams Dr, Prospect. SHIFT TO NEW FRONTIER POLE 1775 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
2W620982	RL:1255 E Main St Wtby CAR V POLE	RL:1255 E Main St Wtby CAR V POLE Replaced 8602 45/2 transfer 50kva	Salvage -M02	108040	1
2W720002	AMM WAKELEE RD,WTBY. Municipal Lig	AMM WAKELEE RD,WTBY. Municipal Light Fault Locate and Repair@ POLE L2A7. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H031783	Rplc. 3 poles to accomodate new tra	Rplc. 3 poles to accomodate new traffic signals Main, Broad, Maple, Rt 2 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
3H032920	JTR, Seabury Dr, Bloomfield, Replac	JTR, Seabury Dr, Bloomfield, Replace DB Cable (ID: 2218)	Salvage -M02	108040	1
3H422062	Prospect St EH / 10.2.14 / P527 / 9	Prospect St EH / 10.2.14 / P527 / 9A AP2-YWO Total Cost Variance Met - Variance :-28.0599 MIN.:-40 MAX.:40	Salvage -M02	108040	1
3H520140	12/16 ESO FOREST ST MANCHESTER CAR	12/16 ESO FOREST ST MANCHESTER CAR VS POLE #2262 / NOT DONE CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
3H521526	RF-758 Rainbow Rd,Windsor,Remove Pr	RF-758 Rainbow Rd,Windsor,Remove Primary SVC and Pad 3215 AP3-YWO Resource Variance Met- Labor 114 <= 32 OR -70.38 <= 30 And Contractor $0 <= 2000	Salvage -M02	108040	1
3H522527	TPA/Rplc P1561 & provide DE guy.Con	TPA/Rplc P1561 & provide DE guy.Conv#281746 billable 5' for com top mount Ant AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H522597	NJB AWC 12/04 HTFD BUCKINGHAM ST HT	NJB AWC 12/04 HTFD BUCKINGHAM ST HTFD. REPLCAE P#2374 35/2 (Stlght UG Feed)	Salvage -M02	108040	1
3H620015	WF-41 Zion St-Htfd-@ mh# 4908, rpl	WF-41 Zion St-Htfd-@ mh# 4908, rpl ug svc.	Salvage -M02	108040	1
3H620101	394 Tolland Tpk.Manch. Disconn.3PH	394 Tolland Tpk.Manch. Disconn.3PH service from P-3954 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H620115	HARTFORD, FRANKLIN AVE @ STANDISH S	HARTFORD, FRANKLIN AVE @ STANDISH ST REBUILD HEX VLT 606 AP3-YWO Resource Variance Met- Labor 62 <= 32 OR -95.41 <= 30 And Contractor $0 <= 2000	Salvage -M02	108040	1
3H620395	Hartford, Broad St - car vs pole 5	Hartford, Broad St - car vs pole 5138- need to replace 150 cobra head AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H620866	HARTFORD, SCARBOROUGH ST city to re	HARTFORD, SCARBOROUGH ST city to replace pole C9051 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H620959	Elliot St Htfd C9103 City Pole 9a	Elliot St Htfd C9103 City Pole 9a Replace 250W head AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H621384	HOMESTEAD AVE, HARTFORD Replace CH8	HOMESTEAD AVE, HARTFORD Replace CH8470 and 250w head AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H621467	MAIN ST, HARTFORD - REPLACE VACUUM	MAIN ST, HARTFORD - REPLACE VACUUM SWITCH MH 731 AP3-YWO Resource Variance Met- Labor 126 <= 32 OR -72.58 <= 30 And Contractor $1577.83 <= 2000	Salvage -M02	108040	1
3H621509	Bidwell St, Manchester - Need to re	Bidwell St, Manchester - Need to replace bad arrester 02 - P-9099 8/11 - HAROH - AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H621565	WF-51+53+55- Maple Ave-Windsor-@ po	WF-51+53+55- Maple Ave-Windsor-@ pole-864, rpl oh svc to building.	Salvage -M02	108040	1
3H621940	85 WOODLAND- HTFD C6266 Replace 250	85 WOODLAND- HTFD C6266 Replace 250w head AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H622038	9/19 - ESO - MANCHESTER, LOVE LN, 9	9/19 - ESO - MANCHESTER, LOVE LN, 9A CAR V POLE 2828 - Replace with 40/2 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H622080	HTFD 3080 MAIN STREET City to repla	HTFD 3080 MAIN STREET City to replace pole CH8668 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H622085	HTFD, Wyllys St, CH9366 replaced 1	HTFD, Wyllys St, CH9366 replaced 143w led head AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H622137	99 HENDERSON RD, MANCH - PT Conv# 4	99 HENDERSON RD, MANCH - PT Conv# 448570-TPA-Fibertech-ParentConv# 447025	Salvage -M02	108040	1
3H622162	HARTFORD, LYME/ BURNHAM STREET 6373	HARTFORD, LYME/ BURNHAM STREET 6373 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H622496	WF-40-44 Lawrence St-Htfd-@pole-300	WF-40-44 Lawrence St-Htfd-@pole-3002, rpl oh svc to building.	Salvage -M02	108040	1
3H622553	12/7 - RSO - HARTFORD, SEQUIN ST -	12/7 - RSO - HARTFORD, SEQUIN ST - 18' DB POLE 10816 BROKEN, MADE SAFE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H622565	NEW BRITAIN AV, W HTFD - Conv#45560	NEW BRITAIN AV, W HTFD - Conv#455605 - TPA DUE BY 3/19 AP2-YWO Total Cost Variance Met - Variance :17.9129 MIN.:-50 MAX.:50	Salvage -M02	108040	1
3H622617	WF-424-426 New Britain Ave-Htfd-@ m	WF-424-426 New Britain Ave-Htfd-@ mh-2828, rpl ug svc to building. AP2-YWO Total Cost Variance Met - Variance :36.9082 MIN.:-50 MAX.:150	Salvage -M02	108040	1
3H622751	WETHERSFIELD, WELLS RD, RPL POLE#1	WETHERSFIELD, WELLS RD, RPL POLE#1496 40/2 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H720005	12/31 - HAROH - MANCHESTER, CENTE	12/31 - HAROH - MANCHESTER, CENTER ST, EVERSOURCE P-1500 set 35/2 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H720215	WEST HARTFORD S MAIN - 9A - EVERSOU	WEST HARTFORD S MAIN - 9A - EVERSOURCE P-3059 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H720291	HARTFORD, HOMESTEAD AVE C8448 city	HARTFORD, HOMESTEAD AVE C8448 city pole replace 250w head AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H720325	HARTFORD,ANN ST REPLACE A MAINS BET	HARTFORD,ANN ST REPLACE A MAINS BETWEEN SB1607 & SB1831 AP2-YWO Total Cost Variance Met - Variance :-27.189 MIN.:-30 MAX.:30	Salvage -M02	108040	1
3H720396	WF 2/10 - HAROH - BLOOMFIELD, TIMOT	WF 2/10 - HAROH - BLOOMFIELD, TIMOTHY LANE ST LT POLE 6049 - COMP 2/21/17 CCC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H720409	Htfd, Gillet St Replace A mains 2	Htfd, Gillet St Replace A mains 2 sections AP2-YWO Total Cost Variance Met - Variance :-33.7248 MIN.:-50 MAX.:50	Salvage -M02	108040	1
3H720573	RSO 2/27 WINDSOR, HANSOM HILL RD -	RSO 2/27 WINDSOR, HANSOM HILL RD - DB FAULT REPLACED HANDHOLE 1232C AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H720590	RSO& AWC, 3/4, HARTFORD, VINE STREE	RSO& AWC, 3/4, HARTFORD, VINE STREET, 9A REPLACED 4/0 TPX 3743 TO 3742 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H720698	WETHERSFIELD, BERLIN TPKE, 9A REPLA	WETHERSFIELD, BERLIN TPKE, 9A REPLACE P1738 45/2 AP2-YWO Total Cost Variance Met - Variance :-47.6215 MIN.:-50 MAX.:50	Salvage -M02	108040	1
3H720736	RSO 3/23 -- WEST HARTFORD, 134 OAKW	RSO 3/23 -- WEST HARTFORD, 134 OAKWOOD AVE- POLE # 1082 - 9A AP2-YWO Total Cost Variance Met - Variance :-11.2451 MIN.:-50 MAX.:50	Salvage -M02	108040	1
3H720896	NJB WEST ST R.H. RPL CUTOUT & RISER	NJB WEST ST R.H. RPL CUTOUT & RISER ON P#1481 CUST OUTAGE ON 6/2/17? @ 5PM AP2-YWO Total Cost Variance Met - Variance :4.7256 MIN.:-50 MAX.:50	Salvage -M02	108040	1
3H720933	AWC/RSO, 4/14, MANCHESTER, E MIDDLE	AWC/RSO, 4/14, MANCHESTER, E MIDDLE TPKE No double pole AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H720981	WF-1221-1223-Broad St-Htfd-@ sb-336	WF-1221-1223-Broad St-Htfd-@ sb-3368, rpl ug svc. AP2-YWO Total Cost Variance Met - Variance :33.2649 MIN.:-50 MAX.:50	Salvage -M02	108040	1
3H721029	EJL - 270 Wetherell St.Manch.Reloca	EJL - 270 Wetherell St.Manch.Relocate 25KVA/Pri./Remove tree guy/P-5188 AP2-YWO Total Cost Variance Met - Variance :113.508 MIN.:-50 MAX.:150	Salvage -M02	108040	1
3H721131	8/22 - HAROH - WINDSOR POQUONOCK AV	8/22 - HAROH - WINDSOR POQUONOCK AVE - REPLACED 2 OH/DB SERVICES P-5248 AP2-YWO Total Cost Variance Met - Variance :3.3243 MIN.:-50 MAX.:50	Salvage -M02	108040	1
3H721195	BLOOMFIELD BLUE HILLS AVE POLE 18 -	BLOOMFIELD BLUE HILLS AVE POLE 18 - 9A AP2-YWO Total Cost Variance Met - Variance :139.4207 MIN.:-50 MAX.:150	Salvage -M02	108040	1
3H721259	Mountain St Htffd POLE 3435 Install	Mountain St Htffd POLE 3435 Installed 90' duplex AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H721262	HARTFORD, NEW BRITAIN AVE REPLACED	HARTFORD, NEW BRITAIN AVE REPLACED 250W HPS P-5038 - COMP 6/8/17 CCC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H721263	HARTFORD, NEW BRITAIN AVE REPLACE 2	HARTFORD, NEW BRITAIN AVE REPLACE 250W HPS P-4962 - COMP 6-8-17 CCC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H721333	5/24 RSO WIndsor Ravine Rd P 3195	5/24 RSO WIndsor Ravine Rd P 3195 Replace pole/crossarm AP2-YWO Total Cost Variance Met - Variance :22.2081 MIN.:-50 MAX.:50	Salvage -M02	108040	1
3H721456	RSO, 6/10, WINDSOR, BROOKVIEW RD, 9	RSO, 6/10, WINDSOR, BROOKVIEW RD, 9A, POLE 4230 REPLACE LED LIGHT AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H721681	South Main St.Manchester Pole 3881	South Main St.Manchester Pole 3881 hit/ Replace with 40/2 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
3H721721	Htfd TRINITY ST - C6843 replace 250	Htfd TRINITY ST - C6843 replace 250w head to new pole AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H721728	RSO/AWC, 7/3, WEST HARTFORD, CONCOR	RSO/AWC, 7/3, WEST HARTFORD, CONCORD STREET REPLACED 150' SEC WITH 4/0 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H721751	7/5 - AWC - WETHERSFIELD, OLD PEPPE	7/5 - AWC - WETHERSFIELD, OLD PEPPERIDGE LA - REPLACED CUTOUT/TERM/RISER AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H721767	7/8 RSO, WINDSOR COLONIAL DR - 9A T	7/8 RSO, WINDSOR COLONIAL DR - 9A TRUCK TOOK DOWN WIRES - RAN 125' SERVICE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H721776	7/9 - HARAWC - WINDSOR, PARK RD - E	7/9 - HARAWC - WINDSOR, PARK RD - EVERSOURCE POLE 156 AP2-YWO Total Cost Variance Met - Variance :69.5323 MIN.:-50 MAX.:150	Salvage -M02	108040	1
3H721840	RSO, 7/13, E HARTFORD, ROBERTS ST,	RSO, 7/13, E HARTFORD, ROBERTS ST, RPLC 8' ARM pole 4138/shift 1/0 ACSR AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H721865	RSO,7/16, WEST HARTFORD, KANE STREE	RSO,7/16, WEST HARTFORD, KANE STREET - INS 3 ELBOW ARR P-3173/REBUILT RISER AP2-YWO Total Cost Variance Met - Variance :-6.6382 MIN.:-50 MAX.:50	Salvage -M02	108040	1
3H721933	Replace OH svc / new attachment poi	Replace OH svc / new attachment point AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H721937	AWC 7/24 MANCHESTER HARTFORD RD 9A	AWC 7/24 MANCHESTER HARTFORD RD 9A - REPLACED QUAD SERVICE FROM P-4700 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H721946	JWL... 119-121 BLUE HILLS AVE. run	JWL... 119-121 BLUE HILLS AVE. run new svc from P5709 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H721986	HARTFORD, ANN ST-C6661 - INSTALL 25	HARTFORD, ANN ST-C6661 - INSTALL 250W HPS AND RECONNECT UG FEED AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H721987	HARTFORD, WALNUT ST - P-CH9493 - IN	HARTFORD, WALNUT ST - P-CH9493 - INSTALL 250W HPS COBRA AND RECONNECT UG FEED AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H721993	7/26 - BLOOMFIELD, CHATEAU MARGAUX	7/26 - BLOOMFIELD, CHATEAU MARGAUX - REPLACED PAD 1719 AP2-YWO Total Cost Variance Met - Variance :51.2571 MIN.:-50 MAX.:150	Salvage -M02	108040	1
3H722032	8/4 - RSO - ROCKY HILL, WEST ST - R	8/4 - RSO - ROCKY HILL, WEST ST - RPL 3-50KVA 120/208 BANK POLE 1406 AP2-YWO Total Cost Variance Met - Variance :-42.569 MIN.:-50 MAX.:50	Salvage -M02	108040	1
3H722035	RSO, 8/5, WINDSOR, KENDRICK LANE -	RSO, 8/5, WINDSOR, KENDRICK LANE - REPLACED HH 1596B AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H722049	DKH - Kennedy Rd, Wsr - Replace rec	DKH - Kennedy Rd, Wsr - Replace recloser upper unit P2982. AP2-YWO Total Cost Variance Met - Variance :.4686 MIN.:-40 MAX.:40	Salvage -M02	108040	1
3H722079	RSO/AWC, 8/9, AVON, LOVELY STREET,	RSO/AWC, 8/9, AVON, LOVELY STREET, P421 9A AP2-YWO Total Cost Variance Met - Variance :-4.5576 MIN.:-50 MAX.:50	Salvage -M02	108040	1
3H722149	453 Wash St Htfd replace 250w Head	453 Wash St Htfd replace 250w Head CH8192 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H722155	JWL @ 877-879 CAPITOL AVE replace	JWL @ 877-879 CAPITOL AVE replace svc from sb3177. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H722156	8/18 - RSO/HAROH - EAST HARTFORD,	8/18 - RSO/HAROH - EAST HARTFORD, SEDGEWICK RD, P2646, 9A AP2-YWO Total Cost Variance Met - Variance :73.2456 MIN.:-50 MAX.:150	Salvage -M02	108040	1
3H722164	8/17 RSO-AWC, WHARTFORD, SEQUIN RD	8/17 RSO-AWC, WHARTFORD, SEQUIN RD 9A - REPLACED POLE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H722171	XL-CDOT 63-633, electrical work to	XL-CDOT 63-633, electrical work to relocate service along Woodland St, Hartford JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
3H722173	XL-CDOT 63-633, electrical work to	XL-CDOT 63-633, electrical work to relocate service along Kent St, Hartford JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
3H722174	8/19 RSO HARTFORD, SWHITNEY ST P#68	8/19 RSO HARTFORD, SWHITNEY ST P#6850 REPLACED 90' SVC WIRE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H722415	175 N. Main St., W. Htfd - REPL OH	175 N. Main St., W. Htfd - REPL OH svc / New attachment point-WORK BY HTFD OH AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H722493	COMP 1/27/18 CCC - WETHERSFIELD, RE	COMP 1/27/18 CCC - WETHERSFIELD, REPLACE ST LT POLE 3230 18' BROWN 70W PTT AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H722608	13 Pinecrest Dr.E.Hartf. Replace op	13 Pinecrest Dr.E.Hartf. Replace open wire service P- 3341 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H723020	4-118 - Relocate facilities for int	4-118 - Relocate facilities for intersection relocation RT 10 - 50% Re-Im JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
3H723179	12/2 - RSO - HARTFORD, ELLIOT ST -	12/2 - RSO - HARTFORD, ELLIOT ST - NEED TO REPLACE 150W C9116 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H723287	HARTFORD, MAIN ST CH7097 replace 25	HARTFORD, MAIN ST CH7097 replace 250 w head when pole is replaced AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H820160	WINDSOR RAINBOW RD P#256 FUSE BLEW	WINDSOR RAINBOW RD P#256 FUSE BLEW ON RISER POLE# 256 AP3-YWO Resource Variance Met- Labor 3 <= 32 OR -3.18 <= 30 And Contractor $1551.87 <= 2000	Salvage -M02	108040	1
3H820327	AWC UG 2/9 HARTFORD, PARK ST SB 938	AWC UG 2/9 HARTFORD, PARK ST SB 938 BURNING SEC INST NE 4/0 3PHSE SRV TO 701 NL-YWO Variance - NU Construction Labor	Salvage -M02	108040	1
3H820563	3150 Main St Htfd C8671 Replace 250	3150 Main St Htfd C8671 Replace 250w head to new city pole AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H820695	4-118 - Relocate facilities to the	4-118 - Relocate facilities to the NEW Town Farms Rd 50% Re-Im JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
3H822312	RF-3 N Fairfield St,Manchester,Relo	RF-3 N Fairfield St,Manchester,Relocate OH SVC	Salvage -M02	108040	1
3H920073	HARTFORD, 877 TOWER AVE @ P5382 ru	HARTFORD, 877 TOWER AVE @ P5382 run new 90ft OH svc, CHANGE METER AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H922469	RF-597 Burnside Ave, East Hartford,	RF-597 Burnside Ave, East Hartford, Replace SVC with #2 TPX AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H923040	RF-21 Bancroft Rd,East Hartford,Rep	RF-21 Bancroft Rd,East Hartford,Replace Damaged OH SVC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H923346	10/25---HTFD-34 Shultas Pl-----new	10/25---HTFD-34 Shultas Pl-----new OH 200A service AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H923407	10/25---BLOOM-11 Mayfair Ct----LINE	10/25---BLOOM-11 Mayfair Ct----LINEWORK REQUIRE TRIPLEX NEEDS TO BE CHANGE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H923415	CR- 60-62 ENFIELD ST HARTFORD, REPL	CR- 60-62 ENFIELD ST HARTFORD, REPLACE OH SVC OFF POLE 4956 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H923418	11/5---W HTFD-94 Flagg Rd-----OH 20	11/5---W HTFD-94 Flagg Rd-----OH 200A service upgrade-power off at pole AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H923519	CR-5 BUCKBOARD LN AVON, REPLACE OH	CR-5 BUCKBOARD LN AVON, REPLACE OH SVC OFF POLE 3518 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3H923696	RF-185 Main St,Manchester,Pole#5223	RF-185 Main St,Manchester,Pole#5223, Replace SVC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L520898	HPS 100W PTT @ PID 79 - COMPLETED 1	HPS 100W PTT @ PID 79 - COMPLETED 11/6/15 HARES1 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L620438	WESTPORT POLE 29551 100 MH PDL - CO	WESTPORT POLE 29551 100 MH PDL - COMPLETED 3/18/16 NTW	Salvage -M02	108040	1
3L620719	SOUTH WINDSOR POLE 2977 400 HPS COB	SOUTH WINDSOR POLE 2977 400 HPS COBRA - COMPLETED 3/18/16 TOL	Salvage -M02	108040	1
3L620841	PROSPECT POLE 1597 70 HPS COBRA (SE	PROSPECT POLE 1597 70 HPS COBRA (SEMI TO FULL) - COMPLETED 3/18/16 WTB	Salvage -M02	108040	1
3L620897	BETHEL POLE 29 70 HPS COBRA - COMPL	BETHEL POLE 29 70 HPS COBRA - COMPLETED 3/9/16 NTW	Salvage -M02	108040	1
3L620934	WATERBURY POLE G7635 400 HPS FLOOD	WATERBURY POLE G7635 400 HPS FLOOD - COMPLETED 3/11/16 WTB AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L620966	STAMFORD POLE 17 70 HPS PTT - COMP	STAMFORD POLE 17 70 HPS PTT - COMPLETED 3/18/16 NTW	Salvage -M02	108040	1
3L620985	WINDSOR POLE 2987 70 HPS COBRA - CO	WINDSOR POLE 2987 70 HPS COBRA - COMPLETED 3/18/16 TOL	Salvage -M02	108040	1
3L620990	BEACON FALLS POLE 22721 250 HPS COB	BEACON FALLS POLE 22721 250 HPS COBRA - COMPLETED 3/18/16 WTB	Salvage -M02	108040	1
3L620993	WATERBURY POLE 63621 400 HPS COBRA	WATERBURY POLE 63621 400 HPS COBRA - COMPLETED 3/18/16 WTB	Salvage -M02	108040	1
3L620994	WATERTOWN POLE 6112 70 HPS COBRA -	WATERTOWN POLE 6112 70 HPS COBRA - COMPLETED 3/18/16 WTB	Salvage -M02	108040	1
3L620995	WINDSOR POLE 2652 70 HPS COBRA - CO	WINDSOR POLE 2652 70 HPS COBRA - COMPLETED 3/18/16 TOL	Salvage -M02	108040	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
3L620996	MANCHESTER POLE 7984 250 HPS COBRA	MANCHESTER POLE 7984 250 HPS COBRA - COMPLETED 3/18/16 TOL	Salvage -M02	108040	1
3L620999	WATERBURY POLE 5141 100 HPS COBRA -	WATERBURY POLE 5141 100 HPS COBRA - COMPLETED 3/18/16 HAR	Salvage -M02	108040	1
3L621000	MERIDEN POLE 5569 70 HPS COBRA - CO	MERIDEN POLE 5569 70 HPS COBRA - COMPLETED 3/18/16 SIM	Salvage -M02	108040	1
3L621875	STONINGTON POLE 7264 100 HPS PTT 43	STONINGTON POLE 7264 100 HPS PTT 430740 & BROWN SQUARE 175189 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L623404	Municipal Light Fault Locate and Re	Municipal Light Fault Locate and Repair@ POLE C6404 NO POWER AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L721076	HARTFORD POLE 6156 150 HPS COBRA CO	HARTFORD POLE 6156 150 HPS COBRA COMP 4/13 TOL AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L721151	BLOOMFIELD, CHESTNUT HILL RD, P-54	BLOOMFIELD, CHESTNUT HILL RD, P-5481 REMOVED 100W HPS PTT/NEED TO REPLACE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L721835	WATERFORD POLE 3764 50 HPS COBRA CO	WATERFORD POLE 3764 50 HPS COBRA COMPLETED 7/24 CHE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L721945	TORRINGTON POLE 3560 150 HPS COBRA	TORRINGTON POLE 3560 150 HPS COBRA COMPLETED 8/3 CHE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L722556	BLOOMFIELD POLE 5616 100 HPS PTT &	BLOOMFIELD POLE 5616 100 HPS PTT & BROWN SQUARE POLE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L722822	LEDYARD POLE 6045 250 HPS COBRA COM	LEDYARD POLE 6045 250 HPS COBRA COMPLETED 10/24 EHA AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L722823	LEDYARD POLE 96 50 HPS COBRA COMPLE	LEDYARD POLE 96 50 HPS COBRA COMPLETED 10/24 EHA AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L722875	PLYMOUTH POLE 1711 150 HPS PTT FIXT	PLYMOUTH POLE 1711 150 HPS PTT FIXTURE IS WORKING 03/01 NTW AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L820579	STAMFORD POLE 16917 250 HPS COBRA C	STAMFORD POLE 16917 250 HPS COBRA COMPLETED 12/20 NTW AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L820837	FARMINGTON POLE 1076 70 HPS COBRA -	FARMINGTON POLE 1076 70 HPS COBRA - COMP 2/3/18 TOL AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L821505	WATERBURY POLE 7175 150 HPS COBRA C	WATERBURY POLE 7175 150 HPS COBRA COMPLETED 04/09 CHE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L821619	COMP 5/23/18 CCC-LEDYARD POLE 2807	COMP 5/23/18 CCC-LEDYARD POLE 2807 BROWN SQ POLE & 51W PTT 601648 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L821890	RTM-COMP 9/28/18 CCC MERIDEN POLE 4	RTM-COMP 9/28/18 CCC MERIDEN POLE 42 BR SQ & RMV 150 HPS PTT, INST 51W LED PTT AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L821930	COMP 10/03/18 CCC POLE 4032 NEEDS T	COMP 10/03/18 CCC POLE 4032 NEEDS TO BE STRAIGHTENED & NEEDS 28W LED PTT AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L822274	HARTFORD POLE 9052 RMV 92W, INST 92	HARTFORD POLE 9052 RMV 92W, INST 92W COMPLETED 07/20 TOL AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L823415	BRANFORD POLE 5918 RMV 36W, INST 30	BRANFORD POLE 5918 RMV 36W, INST 30W AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3L920794	Pole ID: 4167 RMV 70 HPS PTT INSTAL	Pole ID: 4167 RMV 70 HPS PTT INSTALL 28W LED PTT COMP 2/11/19 CHE1 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3R420243	CD00316-02; 11C14 Resiliency; Recon	CD00316-02; 11C14 Resiliency; Recon. RT 81 w 336 TW pole 602 to 637; WO 3 of 3 AP2-YWO Total Cost Variance Met - Variance :-6.1021 MIN.:-20 MAX.:20	Salvage -M02	108040	1
3R420245	bwg/CD000320 pole replacements&reco	bwg/CD000320 pole replacements&reconductor Rte 80 30R8 BB to 336TW,Killingworth CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
3R420248	MP - CD00320-02 - 30R8 - Reconducto	MP - CD00320-02 - 30R8 - Reconductor RTE 80-BB to 336TW - 2 of 2, Madison MS-YWO Variance - Multiple Setups	Salvage -M02	108040	1
3R420330	CD00283-02 Ashford, RT 44, Knowlto	CD00283-02 Ashford, RT 44, Knowlton Hill Rd (pole 1089) to (pole 1120) CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
3R520161	CD00389-01 Remove Autos & Convert	CD00389-01 Remove Autos & Convert Boston Post Rd, Guilford CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
3R520162	CD00389-03 Convert Tanner Marsh &	CD00389-03 Convert Tanner Marsh & Clapboard Hill & Hang Steps CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
3R520167	CD00387-04 Replace Pad 312 Rt 1	CD00387-04 Replace Pad 312 Rt 1 Guilford CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
3R520199	CD00390-02 - System Resiliency - St	CD00390-02 - System Resiliency - Step Down XFMRs - Wildrose & Sam Hill CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
3R620039	JL 2015 SR highway crossing Locatio	JL 2015 SR highway crossing Location ID 139937542 Pole 946 & 947 CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
3R620095	CD00103-13 11M3 seg 13 resiliency p	CD00103-13 11M3 seg 13 resiliency part 1 AP2-YWO Total Cost Variance Met - Variance :8.3386 MIN.:-30 MAX.:30	Salvage -M02	108040	1
3R620120	BW 2015 SR Highway Crossing, Locati	BW 2015 SR Highway Crossing, LocationID46668676, Pole 3472 & 3473 CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
3R620320	BC-CD00630-02 SR Hwy Xng Upg;Obj ID	BC-CD00630-02 SR Hwy Xng Upg;Obj ID(135331980&139930744), I-691@Lewis Ave 417412 AP2-YWO Total Cost Variance Met - Variance :-4.2222 MIN.:-30 MAX.:30	Salvage -M02	108040	1
3R620361	SR Highway Crossing Upgrades CD0063	SR Highway Crossing Upgrades CD00631-02 Object ID (46795754) E. River Rd	Salvage -M02	108040	1
3R620362	CD00631 SR HIGWY XING UPGRADES OBJE	CD00631 SR HIGWY XING UPGRADES OBJECT ID (46818750) HARTFORD RD	Salvage -M02	108040	1
3R620616	RA CD00571-08 Install 3-167KVA S/D	RA CD00571-08 Install 3-167KVA S/D's Sunset Ave Putnam CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
3R620628	CD00392 - Transfer 35L7-90T from P.	CD00392 - Transfer 35L7-90T from P.7242 to P.6475 - Segment 1 AP2-YWO Total Cost Variance Met - Variance :-45.4462 MIN.:-50 MAX.:50	Salvage -M02	108040	1
3R620629	CD00392 - Reconductor 35L7 Boston P	CD00392 - Reconductor 35L7 Boston Post Rd - Segment 2 WR 1 of 2 CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
3R620630	CD00392 - Reconductor 35L7 Boston P	CD00392 - Reconductor 35L7 Boston Post Rd - Segment 2 WR 2 of 2 CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
3R620743	CD00647-02, 28J1 convert OH, Branfo	CD00647-02, 28J1 convert OH, Branford, 1 of 3 CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
3R621016	CD00471-01Elim. 23U Voluntown S/S C	CD00471-01Elim. 23U Voluntown S/S Conversion Work #1 AP2-YWO Total Cost Variance Met - Variance :6.287 MIN.:-30 MAX.:30	Salvage -M02	108040	1
3R621017	CD00471-01Elim. 23U Voluntown S/S C	CD00471-01Elim. 23U Voluntown S/S Conversion Work #2 AP2-YWO Total Cost Variance Met - Variance :-28.5624 MIN.:-30 MAX.:30	Salvage -M02	108040	1
3R621018	CD00471-01Elim. 23U Voluntown S/S C	CD00471-01Elim. 23U Voluntown S/S Conversion Work #3 CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
3R621019	CD00471-01Elim. 23U Voluntown S/S C	CD00471-01Elim. 23U Voluntown S/S Conversion Work #4 AP2-YWO Total Cost Variance Met - Variance :-32.8857 MIN.:-40 MAX.:40	Salvage -M02	108040	1
3R621020	CD00471-01Elim. 23U Voluntown S/S C	CD00471-01Elim. 23U Voluntown S/S Conversion Work #5 AP2-YWO Total Cost Variance Met - Variance :-18.003 MIN.:-20 MAX.:20	Salvage -M02	108040	1
3R621025	CD00471-01 Elim. 23U Voluntown S/S	CD00471-01 Elim. 23U Voluntown S/S - Convert Machine Shop w/XFbank AP3-YWO Resource Variance Met- Labor 4 <= 32 OR 300 <= 30 And Contractor $351.6 <= 2000	Salvage -M02	108040	1
3R621026	CD00471-01 Recond. & Convert Gate S	CD00471-01 Recond. & Convert Gate St - Place 1Ph. on Phase B AP2-YWO Total Cost Variance Met - Variance :-26.0201 MIN.:-30 MAX.:30	Salvage -M02	108040	1
3R621028	CD00471-01 Elim. 23U Voluntown S/S	CD00471-01 Elim. 23U Voluntown S/S Convert School & Housing Authority Phase A AP2-YWO Total Cost Variance Met - Variance :-25.243 MIN.:-30 MAX.:30	Salvage -M02	108040	1
3R621031	CD00471-02 Conversion Work Install	CD00471-02 Conversion Work Install Step Down XF Rte.165 - Place on Phase C AP2-YWO Total Cost Variance Met - Variance :-28.6336 MIN.:-40 MAX.:40	Salvage -M02	108040	1
3R621032	CD00471-03 Conversion Work Rte.49 S	CD00471-03 Conversion Work Rte.49 South AP2-YWO Total Cost Variance Met - Variance :-25.124 MIN.:-30 MAX.:30	Salvage -M02	108040	1
3R621034	CD00471-04 Conversion Work Install	CD00471-04 Conversion Work Install Step Down XF Rte.49 North AP2-YWO Total Cost Variance Met - Variance :32.2343 MIN.:-40 MAX.:40	Salvage -M02	108040	1
3R621035	CD00471-04 Conversion Work Install	CD00471-04 Conversion Work Install Open Point P#41 Rte.49 North AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3R621036	CD00471-04 Conversion Work Install	CD00471-04 Conversion Work Install Step Down XF Rte.49 North AP2-YWO Total Cost Variance Met - Variance :2.0975 MIN.:-40 MAX.:40	Salvage -M02	108040	1
3R621037	CD00471-05 Conversion Work Install	CD00471-05 Conversion Work Install Step Down XF Shetucket Tpke P#449 AP2-YWO Total Cost Variance Met - Variance :-30.923 MIN.:-40 MAX.:40	Salvage -M02	108040	1
3R621038	CD00471-05 Conversion Work Install	CD00471-05 Conversion Work Install Open Point Btwn. Stepdowns P#2046 AP2-YWO Total Cost Variance Met - Variance :-30.5759 MIN.:-50 MAX.:50	Salvage -M02	108040	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
3R621047	CD00471-09 Conversion Work Forge Hi	CD00471-09 Conversion Work Forge Hill Rd Job 2 AP2-YWO Total Cost Variance Met - Variance :-4.4317 MIN.:-20 MAX.:20	Salvage -M02	108040	1
3R621049	CD00471-09 Conversion Work Inst.Ste	CD00471-09 Conversion Work Inst.Step Down XF's No.Shore & Wylie School Job 4 AP2-YWO Total Cost Variance Met - Variance :-12.178 MIN.:-30 MAX.:30	Salvage -M02	108040	1
3R621050	CD00471-10 Conversion Work Install	CD00471-10 Conversion Work Install Step Down XF Bennett Rd AP2-YWO Total Cost Variance Met - Variance :-26.4673 MIN.:-40 MAX.:40	Salvage -M02	108040	1
3R621058	CD00471-01 Elim. 23U S/S Install 13	CD00471-01 Elim. 23U S/S Install 13B25-160R P#4 w/pole replacements CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
3R720020	CAL - CD00849-01 - Ckt 21M1 MBI Ini	CAL - CD00849-01 - Ckt 21M1 MBI Initiative Design Work, Westport CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
3R720043	CAL - CD00849-01 - Ckt 21M15 MBI In	CAL - CD00849-01 - Ckt 21M15 MBI Initiative Design Work, Weston AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3R720059	CAL - CD00849-01 - Ckt 23K12 MBI In	CAL - CD00849-01 - Ckt 23K12 MBI Initiative Design Work, Westport AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3R720097	CAL - CD00849-01 - Ckt 28A1 MBI Ini	CAL - CD00849-01 - Ckt 28A1 MBI Initiative Design Work, Norwalk AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
3R720326	CD00471-01 Reconfig. Ovhd Lines in	CD00471-01 Reconfig. Ovhd Lines in Front of 23U S/S AP2-YWO Total Cost Variance Met - Variance :-17.2137 MIN.:-40 MAX.:40	Salvage -M02	108040	1
3S321466	CDOT 17-186 - RTE 6 Farmington Road	CDOT 17-186 - RTE 6 Farmington Road Widening - OH 6 of 6 - Scott Swamp Rd JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
3S521081	DB LOOP URD AT DUNCASTER WOOD, GRAN	DB LOOP URD AT DUNCASTER WOOD, GRANBY JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
3S521505	16 BARNARD DR, SIMSBURY / REPLACE O	16 BARNARD DR, SIMSBURY / REPLACE OH SVC W/ #2 TPX	Salvage -M02	108040	1
3S620038	W HTFD, South Main St., Replaced Ne	W HTFD, South Main St., Replaced Network Protector and transformer U-259	Salvage -M02	108040	1
3S620064	SIMSBURY 995 HOPMEADOW WESTMINSTER	SIMSBURY 995 HOPMEADOW WESTMINSTER SCHOOL LINE RELO (PHASE 1) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D321128	cb//high st @ ridge rd, chester//sh	cb//high st @ ridge rd, chester//shift to ATT pole 749 & 750 AP2-YWO Total Cost Variance Met - Variance :28.1567 MIN.:-50 MAX.:150	Salvage -M02	108040	1
4D421399	9/6,ESO,9A,car vp3036 trouble ticke	9/6,ESO,9A,car vp3036 trouble ticket & timesheet in documents AP2-YWO Total Cost Variance Met - Variance :39.5828 MIN.:-50 MAX.:50	Salvage -M02	108040	1
4D520695	NS- P 272 Cow Hill Rd, CL- Shift to	NS- P 272 Cow Hill Rd, CL- Shift to Frontier Pole 272	Salvage -M02	108040	1
4D521360	Notify 299187 (child 311443), Billa	Notify 299187 (child 311443), Billable, DAS pole 1870, Old Saybrook	Salvage -M02	108040	1
4D521524	CDOT 59-161/CD00610, UG civil work	CDOT 59-161/CD00610, UG civil work 35L9/35L7, long hill rd, Guilford, stage1 AP2-YWO Total Cost Variance Met - Variance :-35.8544 MIN.:-40 MAX.:40	Salvage -M02	108040	1
4D620423	MV-MADISON CREWS REPLACED REJECT PO	MV-MADISON CREWS REPLACED REJECT POLE 1170 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D620654	NS- P 692 Cow Hill Rd, KW- Shift to	NS- P 692 Cow Hill Rd, KW- Shift to New Pole, Rmv 600A Disconnects CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
4D620709	CB//GUILFORD, 95 HART RD//RELOCATE	CB//GUILFORD, 95 HART RD//RELOCATE OH SVC	Salvage -M02	108040	1
4D620878	ESO - 6/4 Stevenstown Rd. Westbrook	ESO - 6/4 Stevenstown Rd. Westbrook CAR V POLE 651- FOLLOW UP WORK REQUIRED AP2-YWO Total Cost Variance Met - Variance :99.9865 MIN.:-50 MAX.:150	Salvage -M02	108040	1
4D621010	SH-Convo#399782-(MakeReadyREIMB) -	SH-Convo#399782-(MakeReadyREIMB) - VZ Parent Convo#378446 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D621162	PATROL REPAIRS 30R10 - GUILFORD	PATROL REPAIRS 30R10 - GUILFORD CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
4D621215	(DF) Ple 957 -(R/I) Pole & 1 Ph tpo	(DF) Ple 957 -(R/I) Pole & 1 Ph tpo & 1 Ph tap ESO 9A AP2-YWO Total Cost Variance Met - Variance :94.7836 MIN.:-50 MAX.:150	Salvage -M02	108040	1
4D621244	PATROL REPAIRS, 30R8, MADISON	PATROL REPAIRS, 30R8, MADISON CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
4D621412	ESO- 9A Pole - P 2473- Hemlock Dr,	ESO- 9A Pole - P 2473- Hemlock Dr, KW- FOLLOW UP WORK- Rplc Pole & Shift AP2-YWO Total Cost Variance Met - Variance :50.483 MIN.:-50 MAX.:150	Salvage -M02	108040	1
4D621442	PATROL REPAIRS, 11J45 - BRANFORD	PATROL REPAIRS, 11J45 - BRANFORD AP2-YWO Total Cost Variance Met - Variance :11.1984 MIN.:-20 MAX.:20	Salvage -M02	108040	1
4D621494	S Main St, Deep River/TL-ESO - 9A -	S Main St, Deep River/TL-ESO - 9A - 10/12 Car vs Pole 337 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D621517	Bokum Rd, Essex/TL-11/20/16 9A car	Bokum Rd, Essex/TL-11/20/16 9A car vs pole 156 see attached TT AP2-YWO Total Cost Variance Met - Variance :37.7622 MIN.:-50 MAX.:50	Salvage -M02	108040	1
4D621682	Attanwanhood Trl, #1 Old Saybrook/T	Attanwanhood Trl, #1 Old Saybrook/TL--REPL #4 AL SVC W/#2 70' AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D720127	CB//Guilford, Boston Post Rd @ Notc	CB//Guilford, Boston Post Rd @ Notch Hill Rd//9A follow up,Install lights,ins NL-YWO Variance - NU Construction Labor	Salvage -M02	108040	1
4D720134	Hartlands Dr, #35 Old Saybrook/TL-P	Hartlands Dr, #35 Old Saybrook/TL-POLE 496 - NEED NEW 60' SVC TO HOUSE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D720149	CB//GUILFORD, MOOSE HILL RD//UPGRAD	CB//GUILFORD, MOOSE HILL RD//UPGRADE FUSES/CUTOUTS TO 140K POLE 2 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D720194	CB//MADISON, 57 MIDDLE BEACH RD W//	CB//MADISON, 57 MIDDLE BEACH RD W//NEW SVC, SHIFT POLE/WORKS W TEMP RMVL AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D720220	CB//MADISON, 75 NEW RD//SVC UPGRADE	CB//MADISON, 75 NEW RD//SVC UPGRADE 200A/RPL SVC W #2TPX IF ITS #4TPX AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D720245	Stanford Hill Rd, #32 Essex/TL-REPL	Stanford Hill Rd, #32 Essex/TL-REPL EX OH SVC FROM P#432 ***BACKYARD FEED***	Salvage -M02	108040	1
4D720251	CB//MADISON, HULL RD//RELOCATE SECO	CB//MADISON, HULL RD//RELOCATE SECONDARY,XF (EXISTING CROSS FUSE) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D720272	RSO 2/22 -- WESTBROOK, 798 HORSE HI	RSO 2/22 -- WESTBROOK, 798 HORSE HILL RD- POLE # 2211 - NEEDS 60' OF #2 SERVICE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D720286	48 LINDEN AVE (IN OWENEGO BEACH CLU	48 LINDEN AVE (IN OWENEGO BEACH CLUB) P37670 RPL SVC //PRE CHECK OVER ROOF AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D720484	NS- 1 Sag Ter, WB- Ins 4/0 AL from	NS- 1 Sag Ter, WB- Ins 4/0 AL from New HH 831A, Rmv Oh Svc- P 831 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D720605	TS 7 FERRY LA 40778 EC RMV OH SVC I	TS 7 FERRY LA 40778 EC RMV OH SVC INSTALL OH/DB SVC NOT SURE IF APPOINT REQUIRED AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D720858	RSO GUILFORD, Cornwall Ln -Need to	RSO GUILFORD, Cornwall Ln -Need to Replace 153' #2 OH Service @ P8792 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D720970	(DF) Ple 1229 - (R/I) CV svc & cond	(DF) Ple 1229 - (R/I) CV svc & conduit - EMROD DB DESG (ARDB) AP2-YWO Total Cost Variance Met - Variance :-44.9095 MIN.:-50 MAX.:50	Salvage -M02	108040	1
4D721115	(DF) Midspn Ples 1533-3826- Make OH	(DF) Midspn Ples 1533-3826- Make OH svc Connec - 100A upgd- Residential Overhead AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D721118	NS- 25 Aspen Dr, Mad- FOLLOW UP WOR	NS- 25 Aspen Dr, Mad- FOLLOW UP WORK- RPLC BROKEN DB STREETLIGHT AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D721175	RSO 7/23 - MADISON, 393 COPSE RD- P	RSO 7/23 - MADISON, 393 COPSE RD- POLE # 847- AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D721191	Boston Post Rd, Old Saybrook/TL-7/2	Boston Post Rd, Old Saybrook/TL-7/25-P#1712,P#1714,P#2949,P#2949-1/2. Buchetto CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
4D721230	cb//branford, farm river rd//rpl li	cb//branford, farm river rd//rpl light head p 38780R w full cutoff, shield AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D721307	cb//branford, 15 pawson rd//oh svc	cb//branford, 15 pawson rd//oh svc upgrade AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D721781	PT-2017 Double Poles-Pole# 4149-Old	PT-2017 Double Poles-Pole# 4149-Old Quarry Rd, Guilford CT-Conv# 362600 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D721830	COMP 12/30 CCC-Municipal Light Faul	COMP 12/30 CCC-Municipal Light Fault Locate and Repair@ POLE 93 NO VOLTAGE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4D820623	Roamtree Dr, Old Saybrook/TL-5/4/18	Roamtree Dr, Old Saybrook/TL-5/4/18 replace xfmrs, 3 c/o's @ pole2834	Salvage -M02	108040	1
4E030999	MV-NEW DG PROJECT CD01409-01 FOR CP	MV-NEW DG PROJECT CD01409-01 FOR CP EAST HAMPTON SOLAR 1 LLC CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
4E031581	CDOT 82-320 Refeed lights at St Joh	CDOT 82-320 Refeed lights at St John's Square JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
4E420727	car vs pole 1561 6/30/14	car vs pole 1561 6/30/14 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E420733	74 MIDDLE HADDAM RD E HMPTN AT NEW	74 MIDDLE HADDAM RD E HMPTN AT NEW P-40 INST PRI RISER, PAD XF, SVC AP3-YWO Resource Variance Met- Labor 12 <= 32 OR 29.54 <= 30 And Contractor $1020.59 <= 2000	Salvage -M02	108040	1
4E520935	RA CDOT 163-203 RT 66, Bridge#0049	RA CDOT 163-203 RT 66, Bridge#00490 over Natchaug River, Windham - stage 1 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
4E520936	RA CDOT 163-203 RT 66, Bridge#0049	RA CDOT 163-203 RT 66, Bridge#00490 over Natchaug River, Windham - stage 2 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
4E521680	TW Verizon antenna billable make re	TW Verizon antenna billable make ready Conv 320155 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E620127	COLCHESTER AVE E HMPTN 9A AT FRO	COLCHESTER AVE E HMPTN 9A AT FRONTIER POLE 64, REPL XF, SHIFT FACILITIES AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E620254	JK>POLE 651--REPLACE POLE W/35', AN	JK>POLE 651--REPLACE POLE W/35', ANCHOR, SECONDARY & SERVICE	Salvage -M02	108040	1
4E620324	491 COOK HILL RD LEB REPL 4 POLES,	491 COOK HILL RD LEB REPL 4 POLES, 3 SPANS OF, INS STUB POLE & ANC, SHIFT FAC's CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
4E620345	Elec Maint Trouble Call - Repairs/O	Elec Maint Trouble Call - Repairs/Obsolescence OH (AROH)	Salvage -M02	108040	1
4E621047	(CH) EAST HADDAM_TO WRITE_ESO 7/10	(CH) EAST HADDAM_TO WRITE_ESO 7/10 Mill rd East Haddam pole 2311 AP2-YWO Total Cost Variance Met - Variance :148.1196 MIN.:-50 MAX.:150	Salvage -M02	108040	1
4E621233	JK>PAD 533--EXTEND DB SEC TO (3) NE	JK>PAD 533--EXTEND DB SEC TO (3) NEW HH'S FOR CONDO UNITS NL-YWO Variance - NU Construction Labor	Salvage -M02	108040	1
4E621328	BC - CDOT 41-118 - Relocate facilit	BC - CDOT 41-118 - Relocate facilities on RT 66 for bridge replacement STAGE 1 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
4E621348	(CH) P#3720: WORK COMP'D_ESO 9/3_CA	(CH) P#3720: WORK COMP'D_ESO 9/3_CAR V POLE_SET & SHFT'D NEW AP2-YWO Total Cost Variance Met - Variance :70.5819 MIN.:-50 MAX.:150	Salvage -M02	108040	1
4E621449	(CH) HH#385A: CHG LAWNBOX & TAG_HH#	(CH) HH#385A: CHG LAWNBOX & TAG_HH#385B: CHG POLYCRETE & TAG. AP2-YWO Total Cost Variance Met - Variance :-20.3294 MIN.:-50 MAX.:50	Salvage -M02	108040	1
4E720228	(CH) HH#313A: NEED TO CHG COVER_HH#	(CH) HH#313A: NEED TO CHG COVER_HH#311G: COMP'D_FAULT LOCATED/RPR'D/CHG'D AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720235	(CH) P#437: WORK COMP'D_RSO/AWC 2/	(CH) P#437: WORK COMP'D_RSO/AWC 2/21_REPLACED ROTTED POLE & SHFT'D AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720266	(CH) HH#204A: CHG HDP TO POLYCRETE_	(CH) HH#204A: CHG HDP TO POLYCRETE_DISC/RE-CONN SVC FOR SOCKET CHANGE-OUT. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720331	32 FERNWOOD DR COLCH AT P- 2298 FTR	32 FERNWOOD DR COLCH AT P- 2298 FTR POLE IS SET, SHIFT FACILITIES. DBL POLES AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720341	3/2 MIDDLETOWN, WESTLAKE RD, YELLOW	3/2 MIDDLETOWN, WESTLAKE RD, YELLOW TAG Y-18557-2017 ** 17B-2340 *** AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720362	(CH) P#5438 - P#5439: SPLICE OUT WH	(CH) P#5438 - P#5439: SPLICE OUT WHAT LOOKS LIKE TREE GROWTH AROUND CONDUCTOR. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720394	RSO/AWC 3/15 PORTLAND, HIGH ST POLE	RSO/AWC 3/15 PORTLAND, HIGH ST POLE 1082 SVC REPLACED AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720401	MN LAKE DR E HMPTN AT P-244 REPLACE	MN LAKE DR E HMPTN AT P-244 REPLACE POLE, SHIFT FACILITIES. THIS IS A 9A. AP2-YWO Total Cost Variance Met - Variance :-10.9133 MIN.:-50 MAX.:50	Salvage -M02	108040	1
4E720451	(CH) P#97: WORK COMP'D_RSO 3/30-3/3	(CH) P#97: WORK COMP'D_RSO 3/30-3/31_9A_FRNTR SET_WE SHFT'D AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720454	(CH) P#207: CHG DROP_MTR DEPT TO CH	(CH) P#207: CHG DROP_MTR DEPT TO CHG MTR #97987663. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720474	(CH) P#2427: RPL EXIST'G OH/DB SVC	(CH) P#2427: RPL EXIST'G OH/DB SVC WITH NEW 4/0 OH/DB SVC_85' AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720481	(CH) P#474: WRK COMP'D_RSO 4/3_ RPL	(CH) P#474: WRK COMP'D_RSO 4/3_ RPL'D X-ARM__P#5311: NEED TO RPL X-ARM AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720504	JV RSO 4/7 WINDHAM, BEACON RD - REP	JV RSO 4/7 WINDHAM, BEACON RD - REPOLACED 200'AL SVC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720505	(CH) P#3444: WRK COMP'D_RSO/AWC/RSO	(CH) P#3444: WRK COMP'D_RSO/AWC/RSO 4/8_9A AP3-YWO Resource Variance Met- Labor 19 <= 32 OR 35.64 <= 30 And Contractor $1435.56 <= 2000	Salvage -M02	108040	1
4E720513	RSO 4/9/17 Jurczyk, Franklin - rep	RSO 4/9/17 Jurczyk, Franklin - replaced arrestors @ 383 & 385, replace OH xfrm AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720539	JK>HH6833 (LAWN BOX)--REPLACE 17 X	JK>HH6833 (LAWN BOX)--REPLACE 17 X 30 LAWN BOX AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720569	JV 66 Back Rd Windham Ct replace se	JV 66 Back Rd Windham Ct replace secondary pole with svc riser AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720622	JV 60 LOVERS LN WINDHAM INST OH XFM	JV 60 LOVERS LN WINDHAM INST OH XFMR RPLC PL TOP SPCR INST OH SVC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720707	JK>POLE 102--REPLACE POLE & SPAN OF	JK>POLE 102--REPLACE POLE & SPAN OF SEC/SVC FOR OH TRESPASS AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720807	JV Spring View Windham- between pad	JV Spring View Windham- between pad#92 & #93 requires replmt ** 17B-5319 *** CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
4E720811	RSO/AWC 5/24 COLCHESTER, LEBANON AV	RSO/AWC 5/24 COLCHESTER, LEBANON AVE (RT 16) 9A POLE 3 1/4 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E720849	RSO/EH - 5/26 MIDDLETOWN, WASHINGTO	RSO/EH - 5/26 MIDDLETOWN, WASHINGTON ST - 9A P3088 STROM / HOAR AP2-YWO Total Cost Variance Met - Variance :80.0182 MIN.:-50 MAX.:150	Salvage -M02	108040	1
4E721001	JK>POLE 867--REPLACE TERMINATOR AT	JK>POLE 867--REPLACE TERMINATOR AT RISER POLE, RESORE POWER TO NORMAL AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E721058	JK>POLE 242--RMV 3PH PRI RISER, DB	JK>POLE 242--RMV 3PH PRI RISER, DB CABLE, 3PH SVC TO BLDG FOR DEMO (7 MTRS) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E721241	(CH) P#4204: CHG OH DROP_#2 TPX_45'	(CH) P#4204: CHG OH DROP_#2 TPX_45'_MTR DEPT TO CHG MTR #98849099. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E721256	RSO 8/6 MIDDLETOWN, CRYSTAL LAKE RD	RSO 8/6 MIDDLETOWN, CRYSTAL LAKE RD PASCARELLI AP2-YWO Total Cost Variance Met - Variance :32.0064 MIN.:-50 MAX.:150	Salvage -M02	108040	1
4E721257	(CH) PAD#4263: EXTEND PRIM'Y TO PAD	(CH) PAD#4263: EXTEND PRIM'Y TO PAD#4264_UNITS 5-8, 18-21_PHASE 2 AP2-YWO Total Cost Variance Met - Variance :-28.7598 MIN.:-50 MAX.:50	Salvage -M02	108040	1
4E721709	Elec Maint Trouble Call - Repairs/O	Elec Maint Trouble Call - Repairs/Obsolescence OH (AROH) AP2-YWO Total Cost Variance Met - Variance :-1.0265 MIN.:-50 MAX.:50	Salvage -M02	108040	1
4E721884	MN 426 CABIN RD COLCH AT P-2297 RE	MN 426 CABIN RD COLCH AT P-2297 REPLACE OH SVC, MIDSPAN,10 FT OFF OF POLE. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E820604	RA CDOT 163-203 RT 66 - outage sou	RA CDOT 163-203 RT 66 - outage south side of bridge - JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
4E820807	(CH) P#1868: CHG OH DROP_DAMANGED D	(CH) P#1868: CHG OH DROP_DAMANGED DURING MARCH STORMS AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4E821066	BC - CDOT 41-118 - Relocate facilit	BC - CDOT 41-118 - Relocate facilities on RT 66 for bridge replacement STAGE 2 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
4E920002	RA Project CDOT 052-091 RT 207 Fran	RA Project CDOT 052-091 RT 207 Franklin JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
4E921852	MJG - CD01111-01 - Install TR 22R1-	MJG - CD01111-01 - Install TR 22R1-91T on Pole 550 Founders Road AP2-YWO Total Cost Variance Met - Variance :26.2659 MIN.:-30 MAX.:30	Salvage -M02	108040	1
4M221036	pole 2067 prim de/3ph. riser pole s	pole 2067 prim de/3ph. riser pole splitting. NEED to repl & shift now E. Cook	Salvage -M02	108040	1
4M320057	Pole 1253 -40/3 pole has been set,	Pole 1253 -40/3 pole has been set, (R/I) anc- Guy & Pole top, Shift wires &Light AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4M910087	Replace 300A Solids with 600A Disco	Replace 300A Solids with 600A Disconnects	Salvage -M02	108040	1
4N030544	PD-14 Boulevard Court N. London/Rep	PD-14 Boulevard Court N. London/Repl OH svc drop wit 65ft #2TPX from P# 6357	Salvage -M02	108040	1
4N031326	AWC-MV- I/R 250 MID-SPAN OH SVC	AWC-MV- I/R 250 MID-SPAN OH SVC	Salvage -M02	108040	1
4N320643	O Colony Rd,P1840,OL(P4031 Swan Av)	O Colony Rd,P1840,OL(P4031 Swan Av)/Elec Maint T Call - Repairs/Obsol OH (AROH) AP2-YWO Total Cost Variance Met - Variance :11.5968 MIN.:-50 MAX.:50	Salvage -M02	108040	1
4N421261	07/03/14 Pole 5013 replace mh 100 w	07/03/14 Pole 5013 replace mh 100 w head ESO AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N520050	RA Project CDOT 113-107 - relocate	RA Project CDOT 113-107 - relocate facilities for bridge construction Stage 1 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
4N520390	STONINGTON COTTRELL ST - HPS 150W C	STONINGTON COTTRELL ST - HPS 150W COBRA @ PID 2401 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N521143	08/15 ESO LAWRENCE CT PRESTON BROK	08/15 ESO LAWRENCE CT PRESTON BROKEN POLE 2469 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N521323	PD-247 Shore Rd/Old Lyme REPLACE PC	PD-247 Shore Rd/Old Lyme REPLACE PCB XFMR P#1911 CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
4N620016	PD-849 Pequot Ave NLD/Replace exist	PD-849 Pequot Ave NLD/Replace existing P# 10836/Replace ASAP pole is leaning.	Salvage -M02	108040	1
4N620201	MM JOSHUATOWN FUSESAVER RECLOSER PO	MM JOSHUATOWN FUSESAVER RECLOSER POLE 481 NL-YWO Variance - NU Construction Labor	Salvage -M02	108040	1
4N620204	SM-WHITEHALL AVE, STONINGTON - CarV	SM-WHITEHALL AVE, STONINGTON - CarVsP2370- Replaced 45' CLASS 2 AP3-YWO Resource Variance Met- Labor 19 <= 32 OR 67.31 <= 30 And Contractor $916.52 <= 2000	Salvage -M02	108040	1
4N620334	GCC / INSTALL A NEW 50KVA XFMR W/CU	GCC / INSTALL A NEW 50KVA XFMR W/CUT-OUT AND NEW 1/0 AL TPX OH SVC TO BUILDING	Salvage -M02	108040	1
4N620359	ESO 1/28 OXOBOXO DAM RD MONTVILLE C	ESO 1/28 OXOBOXO DAM RD MONTVILLE CARVSPOLE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N620422	3/29/16-Tree down, replaced c/o, po	3/29/16-Tree down, replaced c/o, pole #3755 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N620614	PD-18 Bartlett Place WTFD/Install n	PD-18 Bartlett Place WTFD/Install new pole due to woodpecker damage AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N620638	PD-Tillley/Green/Pearl NLD/Parking	PD-Tillley/Green/Pearl NLD/Parking lot overhead service refeeds NL-YWO Variance - NU Construction Labor	Salvage -M02	108040	1
4N620766	GCC / REMOVE AND RELOCATE FACILITIE	GCC / REMOVE AND RELOCATE FACILITIES / STREET LITES	Salvage -M02	108040	1
4N620866	SM-1 LAMBERTS LN, STGN- EVRSRC RPLC	SM-1 LAMBERTS LN, STGN- EVRSRC RPLC 2 POLES INSTALL OH-DB SVC- APPNT REQ AP2-YWO Total Cost Variance Met - Variance :-6.923 MIN.:-50 MAX.:50	Salvage -M02	108040	1
4N620924	PD-Bayonet St P# 11494/Replace faul	PD-Bayonet St P# 11494/Replace fault indicators	Salvage -M02	108040	1
4N621217	ESO 9A - 08/15/16 GREEN HAVEN STONI	ESO 9A - 08/15/16 GREEN HAVEN STONINGTON car v pole 6781 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N621221	ESO 9/1/16-HAWKS NEST RD., OLD LYME	ESO 9/1/16-HAWKS NEST RD., OLD LYME BACKHOE V POLE 761 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N621252	MM SMART SWITCH PROGAM TR POLE 7794	MM SMART SWITCH PROGAM TR POLE 7794 PEQUOT RD 1Q01 NL-YWO Variance - NU Construction Labor	Salvage -M02	108040	1
4N621263	PD-P# 105S Ocean Ave Car vs Pole	PD-P# 105S Ocean Ave Car vs Pole AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N621319	Elec Svc New Com/Ind DESG (DN)	Elec Svc New Com/Ind DESG (DN)	Salvage -M02	108040	1
4N621398	ESO 9A 9/7/16-Cow Hill Rd., Groton/	ESO 9A 9/7/16-Cow Hill Rd., Groton/Mystic /NEED TO RETURN & FIX PRIMARY RISER AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N621399	ESO 9A 9/5/ Pole 20865 - Fellows	ESO 9A 9/5/ Pole 20865 - Fellows Rd., (Rt 163), Montville AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N621416	PD-187 West Main St East Lyme/Car V	PD-187 West Main St East Lyme/Car VS P# 1224 NL-YWO Variance - NU Construction Labor	Salvage -M02	108040	1
4N621419	MM POLE 2551 S. LEDYARD RD10/14/201	MM POLE 2551 S. LEDYARD RD10/14/2016 REPLACED INSULTATOR ALL WORK COMPLETE	Salvage -M02	108040	1
4N621464	MM STUB POLE 2701S 9A ALL WORK COM	MM STUB POLE 2701S 9A ALL WORK COMPLETE DOT hit pole 2701 notify 491208	Salvage -M02	108040	1
4N621470	MM STUB POLE, 95s ANCHOR, SPAN GUY,	MM STUB POLE, 95s ANCHOR, SPAN GUY, SDWLK GUY COLMANST NEW LONDON notif #490181 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N621483	SM-249 PALMER NECK RD, STGN- RPLC P	SM-249 PALMER NECK RD, STGN- RPLC POLE/, INSTL XFMR/INSTL OH-DB SVC AP2-YWO Total Cost Variance Met - Variance :82.3711 MIN.:-50 MAX.:150	Salvage -M02	108040	1
4N621485	MM SMART SWITCH 11Y6 POLES 405 W MA	MM SMART SWITCH 11Y6 POLES 405 W MAIN ST EAST LYME NL-YWO Variance - NU Construction Labor	Salvage -M02	108040	1
4N621600	ESO 10/19 RAYMOND HILL RD, MONTVILL	ESO 10/19 RAYMOND HILL RD, MONTVILLE - CAR VS P#4492 MADE SAFE FOR NOW AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N621608	11/23/16 9A CAR V POLE - HARTFORD N	11/23/16 9A CAR V POLE - HARTFORD NEW LOND TPKE MNTVILE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N621635	GCC / FRONTIER I&R POLE / SHIFT FAC	GCC / FRONTIER I&R POLE / SHIFT FACILITES/INSTALL NEW SVC RISER TO DB SVC TO HOM AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N621724	MM REPLACE SERVICE RSO 12/20 NL, BR	MM REPLACE SERVICE RSO 12/20 NL, BRAEMER PL P 7607 ALL WORK COMPLETE	Salvage -M02	108040	1
4N621741	MM REPLACE SERVICE 48 LONGVIEW ST,	MM REPLACE SERVICE 48 LONGVIEW ST, NEW LODON ALL WORK COMPLETE	Salvage -M02	108040	1
4N621769	MM ALL WORK COMPLETE GORTON ST,POLE	MM ALL WORK COMPLETE GORTON ST,POLE 1740 - REPLACED 70' 2 STRAND SERVICE	Salvage -M02	108040	1
4N720015	RSO 1/2/, LIBERTY ST, STONINGTON -	RSO 1/2/, LIBERTY ST, STONINGTON - 9A - pole # 7004- needs to be replaced CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
4N720030	RSO/AWC - 1/6 LEDYARD, IRON ST 9A P	RSO/AWC - 1/6 LEDYARD, IRON ST 9A P1247 LEMIEUX/LEARNED/BONGO/ DOWLING AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N720046	MM REPLACE SERVICE 9A SPITHEAD RD.	MM REPLACE SERVICE 9A SPITHEAD RD. WATERFORD @ P1558	Salvage -M02	108040	1
4N720048	GCC / ROTTEN POLE / FRONTIER I&R PO	GCC / ROTTEN POLE / FRONTIER I&R POLE / EVERSOURCE TO SHIFT ONTO AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N720237	PD-Pequot Ct and West End Ave Niant	PD-Pequot Ct and West End Ave Niantic set new 45-2 & shifted facilities AP2-YWO Total Cost Variance Met - Variance :85.6706 MIN.:-50 MAX.:150	Salvage -M02	108040	1
4N720247	SM-265 NW CRNR RD, N STGN- FRNT RPL	SM-265 NW CRNR RD, N STGN- FRNT RPLC PLE, OH XFMR, OH-DB SVC AP3-YWO Resource Variance Met- Labor 26 <= 32 OR 166.67 <= 30 And Contractor $571.4 <= 2000	Salvage -M02	108040	1
4N720274	PD-9 Fairhaven Rd East Lyme/Disconn	PD-9 Fairhaven Rd East Lyme/Disconnect-reconnect OH svc for upgrade. AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N720369	SM-PURA DBL PLE P234- ELM ST, GRTN	SM-PURA DBL PLE P234- ELM ST, GRTN AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N720562	SM Y-18695-2017 YELLOW TAG REPLACE	SM Y-18695-2017 YELLOW TAG REPLACE CAPACITOR P#3051 AP2-YWO Total Cost Variance Met - Variance :30.1932 MIN.:-50 MAX.:50	Salvage -M02	108040	1
4N720646	MM NEW MID SPAN SERVICE POLE 1200 H	MM NEW MID SPAN SERVICE POLE 1200 HOUSE 213 SHORE RD MLC METER SER TO SET METER AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N720868	MM RELOCATE POLE LINE FOR NEW LONDO	MM RELOCATE POLE LINE FOR NEW LONDON ROAD WIDENING notify #529767 AP2-YWO Total Cost Variance Met - Variance :-4.1735 MIN.:-40 MAX.:40	Salvage -M02	108040	1
4N720921	MM WTFD, E. Wood - Replace 50' #2 O	MM WTFD, E. Wood - Replace 50' #2 OH Service ALL WORK COMPLETE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N720977	GCC / REMOVE AND INSTALL CUT-OUTS A	GCC / REMOVE AND INSTALL CUT-OUTS AT TWO LOCATIONS, SAME ROAD AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N721015	GCC / RMV XFMR OVERLOADED / INSTALL	GCC / RMV XFMR OVERLOADED / INSTALL A NEW XFMR AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N721068	COMPLETED 6/27 CCC - Fault Locate a	COMPLETED 6/27 CCC - Fault Locate and Repair@ POLE 2986 NO POWER UG AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N721070	COMPLETED 6/29 CCC-Fault Locate and	COMPLETED 6/29 CCC-Fault Locate and Repair@POLE 2794 NO POWER UG AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N721078	GCC / REMOVE CUT-OUTS AND INSTALL A	GCC / REMOVE CUT-OUTS AND INSTALL A NEW CUT-OUTS AP2-YWO Total Cost Variance Met - Variance :-15.0233 MIN.:-50 MAX.:50	Salvage -M02	108040	1
4N721153	PD-27 Lincoln Rd WTFD/Disconnect-re	PD-27 Lincoln Rd WTFD/Disconnect-reconnect for svc upgrade/Net meter AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N721175	MM REPLACE 75' SERVICE AT POLE 25	MM REPLACE 75' SERVICE AT POLE 2500 ALL WORK COMPLETE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N721203	SM-240 BOSTON POST RD, WTRFRD- RMV	SM-240 BOSTON POST RD, WTRFRD- RMV OH SVC AND INSTL OH-DB AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N721319	PD-7/28 INST. NEW XFORMER AND 3/CUT	PD-7/28 INST. NEW XFORMER AND 3/CUT OUTS ON 7057 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N721464	PD-44 Indianola Rd Niantic/Replace	PD-44 Indianola Rd Niantic/Replace OH svc drop AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N721466	RSO 8/17 - SALEM, WEST RD - PAD # 1	RSO 8/17 - SALEM, WEST RD - PAD # 142 / NEED TO RETURN FIX PROBLEM AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
4N721497	GCC / REMOVE AND INSTALL OVERHEAD S	GCC / REMOVE AND INSTALL OVERHEAD SERVICE TO HOME AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N721645	MM RPLCE 3 LEAKING XFRMRS ALL WORK	MM RPLCE 3 LEAKING XFRMRS ALL WORK COMPLETE CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
4N721805	GCC / RMV EXISTING OVERHEAD SVC AND	GCC / RMV EXISTING OVERHEAD SVC AND INSTALL A NEW OVERHEAD SVC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N820210	MM REPLACE DAMAGED SERVICE WIRE FRO	MM REPLACE DAMAGED SERVICE WIRE FROM POLE 1517TO HOUSE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N820536	Quanaduck Rd, Stonington/TL-02-26-1	Quanaduck Rd, Stonington/TL-02-26-18 REPLACED XFMR WITH ABOVE GROUND XFMR & PAD AP2-YWO Total Cost Variance Met - Variance :27.7279 MIN.:-50 MAX.:50	Salvage -M02	108040	1
4N820787	GCC / I&R XFMR AND INSTALL A NEW 15	GCC / I&R XFMR AND INSTALL A NEW 150' OVERHEAD SERVICE TO HOME AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N821095	MM REPLACE 100' SERVICE WIRE NEW 20	MM REPLACE 100' SERVICE WIRE NEW 200A MTR BY MTR SERVC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N821586	GCC / I&R OVERHEAD SERVICE TO HOME	GCC / I&R OVERHEAD SERVICE TO HOME	Salvage -M02	108040	1
4N921005	PD- South Water Street N. London/Re	PD- South Water Street N. London/Replace crushed polycrete handhold AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
4N921785	10/23/19 37 ORCHARD ST - STONINGTON	10/23/19 37 ORCHARD ST - STONINGTON- P2770-6 Replcd 30 FT #2 oh svc	Salvage -M02	108040	1
5D030998	DG P#2652, FRNTR POLE RPLC , CLP SH	DG P#2652, FRNTR POLE RPLC , CLP SHIFTED, 25KVA XFMR & CO JOB COMP	Salvage -M02	108040	1
5D221491	DG P#2411 RPLC 1 SECT NEUTRAL W/TPX	DG P#2411 RPLC 1 SECT NEUTRAL W/TPX, 1 SECT TPX XROAD, OH/DB SVC RSR	Salvage -M02	108040	1
5D420614	RA CD00086-04 1ph 1/0 to 3ph 336 T	RA CD00086-04 1ph 1/0 to 3ph 336 TW reconductor RT 6 Chaplin AP2-YWO Total Cost Variance Met - Variance :9.3973 MIN.:-10 MAX.:10	Salvage -M02	108040	1
5D520552	CD00450-01 RIGHT OF WAY FROM RIVER	CD00450-01 RIGHT OF WAY FROM RIVER CROSSING AT 12STUNNEL TO RT 169 NL-YWO Variance - NU Construction Labor	Salvage -M02	108040	1
5D520553	BC - CD00450-02 - New 3PH Ovrbld,Re	BC - CD00450-02 - New 3PH Ovrbld,Re-cond. & Convert 1PH Undrbld (1 of 5) 472157 CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
5D520555	BC - CD00450-02 - 1PH, Re-cond. & C	BC - CD00450-02 - 1PH, Re-cond. & Convert (4.8 to 23)kV, Club House Rd (3 of 5) CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
5D520569	CD00450-01 New 3PH 556 TW Overbuild	CD00450-01 New 3PH 556 TW Overbuild, Paper Mill Rd, Town of Lisbon (Part 1 of 5) NO AWOCS-AWOCS REASON CODE AND DESCRIPTION NOT FOUND.	Salvage -M02	108040	1
5D521065	RA Power Survey 307373, Billable, D	RA Power Survey 307373, Billable, DAS pole 1754, Sterling	Salvage -M02	108040	1
5D620106	RA CD00078-02 JC B/B 12S1/21D3 co	RA CD00078-02 JC B/B 12S1/21D3 convert RT 138 p80 (600's) to p50 (600's) AP2-YWO Total Cost Variance Met - Variance :.8963 MIN.:-20 MAX.:20	Salvage -M02	108040	1
5D620111	RA CD00078-06 JC B/B 12S1/21D3 :	RA CD00078-06 JC B/B 12S1/21D3 : install 3-333KVA S/D RT 164 Griswold AP2-YWO Total Cost Variance Met - Variance :-11.2133 MIN.:-20 MAX.:20	Salvage -M02	108040	1
5D620198	DG P#1423 10 BIG HORN LN WOODSTOCK	DG P#1423 10 BIG HORN LN WOODSTOCK RPLC OH SVC MOVE MIDSPAN CLOSER TO POLE	Salvage -M02	108040	1
5D620475	RD 2016 Def Pole Replacement - P179	RD 2016 Def Pole Replacement - P1790 - Brockway Rd	Salvage -M02	108040	1
5D620545	1148 PLAINFIELD PIKE, STERLNG, POL	1148 PLAINFIELD PIKE, STERLNG, POLE#218, INST NEW 1/0 QPX, 3-PH, 120/208 OH/SVC	Salvage -M02	108040	1
5D620573	RA CD00078-02 JC B/B 12S1/21D3 :	RA CD00078-02 JC B/B 12S1/21D3 : Pine Rd - Convert/Recon from RT 138 end AP2-YWO Total Cost Variance Met - Variance :-20.7484 MIN.:-30 MAX.:30	Salvage -M02	108040	1
5D620574	RA CD00078-02 JC B/B 12S1/21D3 :	RA CD00078-02 JC B/B 12S1/21D3 : Pine Rd - fill gap - create N.O. tie point AP2-YWO Total Cost Variance Met - Variance :-33.7995 MIN.:-40 MAX.:40	Salvage -M02	108040	1
5D620575	RA CD00078-02 JC B/B 12S1/21D3 :	RA CD00078-02 JC B/B 12S1/21D3 : Convert Goldstein Rd AP2-YWO Total Cost Variance Met - Variance :-47.7583 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5D620845	RA CD00078-02 JC B/B 12S1/21D3 co	RA CD00078-02 JC B/B 12S1/21D3 convert RT 138 p50 (600's) to 12S1 r.o.w. AP2-YWO Total Cost Variance Met - Variance :7.3617 MIN.:-20 MAX.:20	Salvage -M02	108040	1
5D620880	RA CD00078-02 JC B/B 12S1/21D3 pr	RA CD00078-02 JC B/B 12S1/21D3 pre-build DB Slater Village Shopping Center AP2-YWO Total Cost Variance Met - Variance :-33.6523 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5D620884	RA CD00078-02 install 333KVA S/D Ta	RA CD00078-02 install 333KVA S/D Taylor Hilll Rd off RT 138 Griswold AP2-YWO Total Cost Variance Met - Variance :-31.9432 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5D621134	BC - CD00450-08 - Re-cond, Inst/Rmv	BC - CD00450-08 - Re-cond, Inst/Rmv River/RR Xing Structures, Town of Preston CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
5D621289	DG P#1258 96 RED BRIDGE RD THOMPSON	DG P#1258 96 RED BRIDGE RD THOMPSON FRNTR POLE RPLC CLP TO SHIFT CO P#1259 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5D621348	DG P#981 RSO 12/24 CONVERSE RD, WOO	DG P#981 RSO 12/24 CONVERSE RD, WOODSTOCK - HBV - WEBB CLP TO SHIFT NOT COMP AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5D720030	DG P#535 KILLINGLY RD POMFRET HBV 1	DG P#535 KILLINGLY RD POMFRET HBV 12-12-16 NO 9A TICKET AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5D720332	EXLEY RD, POLE # 933, FRONTIER REJE	EXLEY RD, POLE # 933, FRONTIER REJECT, SET NEW 40'/2, POLE SHIFT AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5D720504	POLE 286, RSO, 4/28, LISBON, NEWEN	POLE 286, RSO, 4/28, LISBON, NEWENT RD, 9A, STILWELL AP2-YWO Total Cost Variance Met - Variance :10.474 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5D720552	DG P#2493 DOW RD PLAINFIELD FRNTR P	DG P#2493 DOW RD PLAINFIELD FRNTR POLE RPLC CLP TO SHIFT AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5D720556	DG P#1348S ACADEMY HILL RD PLAINFIE	DG P#1348S ACADEMY HILL RD PLAINFIELD FRNTR POLE RPLC CLP TO SHIFT AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5D720575	RSO, 5/5, STARKWEATHER ROAD, 9A GN	RSO, 5/5, STARKWEATHER ROAD, 9A GNESDA, POLE 430, HBV, SHIFT TO NEW POLE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5D720640	135 WESTON RD, P#2497 Elec Maint Po	135 WESTON RD, P#2497 Elec Maint Pole Reject - PRIORITY DESG (IFOH) AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5D720651	39 CANTERBURY RD, POLE#27, SHIFT TO	39 CANTERBURY RD, POLE#27, SHIFT TO NEW POLE#27, REJECT POLE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5D720743	RSO 6/2 GRISWOLD, BITGOOD RD- 9A P1	RSO 6/2 GRISWOLD, BITGOOD RD- 9A P1789 - WEBB/GEMBEL/CIVARDI , NOT COMP AP2-YWO Total Cost Variance Met - Variance :85.6143 MIN.:-50 MAX.:150	Salvage -M02	108040	1
5D720752	DG P#359 6 WESTFORD RD EASTFORD RPL	DG P#359 6 WESTFORD RD EASTFORD RPLC BRKN ARM, CO's, NEED TO INST(3) ARRESTERS AP2-YWO Total Cost Variance Met - Variance :15.2523 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5D720755	RA replace Frontier defective po	RA replace Frontier defective pole 564 Bethel Rd AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5D720768	RSO/AWC, 6/10, THOMPSON, RIVERSIDE	RSO/AWC, 6/10, THOMPSON, RIVERSIDE DRIVE, 9A AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5D720811	DG P#2456 1 BEATTIE AVE THOMPSON FR	DG P#2456 1 BEATTIE AVE THOMPSON FRNTR POLE RPLC, 25 KVA, OH SVC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5D820008	49 N. CHESTNUT ST, POLE#25, INSTALL	49 N. CHESTNUT ST, POLE#25, INSTALL 50KVA , SPLIT CRIB FROM POLE#1570	Salvage -M02	108040	1
5D820187	RSO,2/14, WOODSTOCK, ROCKY HILL ROA	RSO,2/14, WOODSTOCK, ROCKY HILL ROAD AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5D920268	RA Project CDOT 123-066 RT 14 Scotl	RA Project CDOT 123-066 RT 14 Scotland Stage 1 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
5D920489	RA Project CDOT 123-066 RT 14 Scotl	RA Project CDOT 123-066 RT 14 Scotland Stage 2 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
5T520257	CDOT32-148 Mansfield/Cov Re-energiz	CDOT32-148 Mansfield/Cov Re-energize primary over Rte 275 bridge 1of 2 50% reimb JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
5T520636	CB PN CD00462 - replace reject pole	CB PN CD00462 - replace reject pole #7883 Colburn Rd. Stafford 40'/2 CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
5T521327	West Rd, Ellington. BBA P-32007 Ins	West Rd, Ellington. BBA P-32007 Install 45-2 replaced primary riser.	Salvage -M02	108040	1
5T521425	8/12 SPRINGFIELD RD,SOMERS-BBA	8/12 SPRINGFIELD RD,SOMERS-BBA	Salvage -M02	108040	1
5T522069	AWC 12/1 S. MAIN ST, EW - DIG UP ES	AWC 12/1 S. MAIN ST, EW - DIG UP ESI HIT CABLE AP2-YWO Total Cost Variance Met - Variance :-1.3831 MIN.:-40 MAX.:40	Salvage -M02	108040	1
5T522213	ESO 12/9 MAIN ST, SOMERS - MVA CAUS	ESO 12/9 MAIN ST, SOMERS - MVA CAUSED P#313 TO BREAK AP2-YWO Total Cost Variance Met - Variance :39.6471 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5T620092	1/15 RIVER RD,WILLINGTON 9A	1/15 RIVER RD,WILLINGTON 9A AP2-YWO Total Cost Variance Met - Variance :38.8667 MIN.:-50 MAX.:50	Salvage -M02	108040	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
5T620313	Highland Ave, Ellington - P#275, re	Highland Ave, Ellington - P#275, replace 2 missing Fault Indicators	Salvage -M02	108040	1
5T620432	3/17 STOUGHTON RD, EW - TREE TOOK D	3/17 STOUGHTON RD, EW - TREE TOOK DOWN 2 POLES 1964 & 2310 40/2'S	Salvage -M02	108040	1
5T620824	RA CDOT 32-130 Main St., Coventry	RA CDOT 32-130 Main St., Coventry - STA 23+50 relocate 26S JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
5T620828	RA CDOT 32-130 Main St., Coventry	RA CDOT 32-130 Main St., Coventry - STA 21+40 relocate 28s JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
5T621064	Shenipsit Lake Rd, Tolland. BBA P-3	Shenipsit Lake Rd, Tolland. BBA P-35 all work done in field AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T621453	8/7, 9A 196 FrazerFir Rd, SOUTH Win	8/7, 9A 196 FrazerFir Rd, SOUTH Windsor, pole 305 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T621525	ESO 8/22 Conklin Rd Stafford p 7056	ESO 8/22 Conklin Rd Stafford p 7056/ 7060 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T621800	RSO 11/14 HAZARD AVE ENFIELD - 2ND	RSO 11/14 HAZARD AVE ENFIELD - 2ND TIME DIG UP AP2-YWO Total Cost Variance Met - Variance :25.4823 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5T720247	SW, RUGBY LN - INSTALLED MED HH @ P	SW, RUGBY LN - INSTALLED MED HH @ POLE 1 - COMP 6/2/17 CCC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T720350	Lathrop Rd, Covemtry - Extend prima	Lathrop Rd, Covemtry - Extend primary two sections, plz see sketch AP2-YWO Total Cost Variance Met - Variance :20.6548 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5T720375	AWC-OH, 2/25, ENFIELD, TILL STREET,	AWC-OH, 2/25, ENFIELD, TILL STREET, CAR VS POLE 15009 9A AP2-YWO Total Cost Variance Met - Variance :32.6392 MIN.:-50 MAX.:150	Salvage -M02	108040	1
5T720405	Avery St., South Windsor - Relocate	Avery St., South Windsor - Relocate facilities for The Town Road Work	Salvage -M02	108040	1
5T720517	3/8 - AWC - LONG HILL RD,ANDOVER -	3/8 - AWC - LONG HILL RD,ANDOVER - 9A - POLE 337 BROKEN - REPLACED XFMR AP2-YWO Total Cost Variance Met - Variance :-18.835 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5T720571	Fletcher Rd, Enfield - Relocate fac	Fletcher Rd, Enfield - Relocate facilities for the Town of Enfield AP2-YWO Total Cost Variance Met - Variance :-10.4774 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5T720579	WILLINGTON, RIVER RD 9A POLE 220 po	WILLINGTON, RIVER RD 9A POLE 220 pole replaced by Frontier 3/16 AP2-YWO Total Cost Variance Met - Variance :76.8228 MIN.:-50 MAX.:150	Salvage -M02	108040	1
5T720674	Alice Dr, Coventry. Shift Frontier	Alice Dr, Coventry. Shift Frontier pole sets, Replace open wire sec and XFR'S AP2-YWO Total Cost Variance Met - Variance :-24.9807 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5T720693	JV COVENTRY, SOUTH ST - SHIFT FRONT	JV COVENTRY, SOUTH ST - SHIFT FRONTIER POLES 391, 392 AND 393 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T720704	JV COVENTRY, SOUTH ST - SHIFT FRONT	JV COVENTRY, SOUTH ST - SHIFT FRONTIER POLE 137 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T720747	West Main St 45, Vernon. Install Ra	West Main St 45, Vernon. Install Rayflate kits on 8 location. 2 SETS 4 CONDUITS AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T720857	STAFFORD LAMB RD - PRIORITY REJECT	STAFFORD LAMB RD - PRIORITY REJECT POLE 7651 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T720994	VERNON, E MAIN ST - REPLACED 400W H	VERNON, E MAIN ST - REPLACED 400W HPS FLOOD @ POLE 9s - COMP 5/25/17 CCC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T721048	Mullen Rd, Enfield - Part 3 of 4 -	Mullen Rd, Enfield - Part 3 of 4 - Relocate poles per Town of Enfield AP2-YWO Total Cost Variance Met - Variance :4.5336 MIN.:-40 MAX.:40	Salvage -M02	108040	1
5T721223	Relocate 39E1 23kV From Hamlton Rd.	Relocate 39E1 23kV From Hamlton Rd. to new Schoephoester Rd. Windsor Locks JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
5T721250	5/16 RSO & ESO PUCKER ST,COVENTRY 9	5/16 RSO & ESO PUCKER ST,COVENTRY 9A EW-YWO Variance - Emergent Work	Salvage -M02	108040	1
5T721381	RSO, 5/31, ENFIELD, MOODY ROAD, POL	RSO, 5/31, ENFIELD, MOODY ROAD, POLE 21590 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T721465	6/12 - RSO/AWC - WILLINGTON, HANCOC	6/12 - RSO/AWC - WILLINGTON, HANCOCK RD POLE 1044 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T721538	6/20 - RSO - ANDOVER, SKINNER HILL	6/20 - RSO - ANDOVER, SKINNER HILL RD - REMOVE IDLE 10KVA XFMR P-446 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T721575	Woods Rd, Somers - Extend 1 ph prim	Woods Rd, Somers - Extend 1 ph primary AP2-YWO Total Cost Variance Met - Variance :-24.137 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5T721629	ANDOVER, BEAR SWAMP RD - VOLTAGE CO	ANDOVER, BEAR SWAMP RD - VOLTAGE COMPLAINT - INSTALL 25KVA XFMR P-407 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T721647	6/30 - RSO/AWC - ENFIELD, BRAINARD	6/30 - RSO/AWC - ENFIELD, BRAINARD RD, 9A - EVERSOURCE P-2503 complete in field AP2-YWO Total Cost Variance Met - Variance :29.3618 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5T721689	MOUNTAIN VIEW RD, SOMERS - 9A POLE	MOUNTAIN VIEW RD, SOMERS - 9A POLE 11075-COMPLETE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T721716	AWC 7/9 EAST WINDSOR OMELIA RD - RE	AWC 7/9 EAST WINDSOR OMELIA RD - REPLACED 3 CUTOUTS P-1792 EW-YWO Variance - Emergent Work	Salvage -M02	108040	1
5T721737	RSO, 7/12, ENFIELD, ELM STREET, CAB	RSO, 7/12, ENFIELD, ELM STREET, CABLE FAULT, RPLC FAULT INDICATORS MHC AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T721742	7/13 - RSO/TOLOH - VERNON, TAYLOR S	7/13 - RSO/TOLOH - VERNON, TAYLOR ST - 9A - FRONTIER POLE 1105 AP2-YWO Total Cost Variance Met - Variance :-25.8548 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5T721752	RSO, 7/15, ENFIELD, ELM STREET, POL	RSO, 7/15, ENFIELD, ELM STREET, POLE 2139, REFER TO AWC TO RPLC 9A AP2-YWO Total Cost Variance Met - Variance :35.4939 MIN.:-50 MAX.:150	Salvage -M02	108040	1
5T721771	Pleasant View Dr. Vernon P1733 repl	Pleasant View Dr. Vernon P1733 replace rotten cross arm AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T721785	RSO, 7/19, ENFIELD, POST OFFICE, PO	RSO, 7/19, ENFIELD, POST OFFICE, POLE 12666 - REPLACE OH SVC/REPLACE METER AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T721787	Hall HillRd.,23,Somers,install 4/0q	Hall HillRd.,23,Somers,install 4/0qpxsec,(2) risers 200,400amp 3phase 120/208 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T721877	8/3 - RSO - SULLIVAN AVE, SOUTH WIN	8/3 - RSO - SULLIVAN AVE, SOUTH WINDSOR, P-5026 - UPGRADE QUAD - LOW VOLTAGE AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T721885	Diamond Ledge Rd.,6,Stafford run 12	Diamond Ledge Rd.,6,Stafford run 120'2tpx 100amp meter p-3723 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T721904	8/7 - RSO/AWC - PLEASANT VALLEY RD,	8/7 - RSO/AWC - PLEASANT VALLEY RD,SW-GENERATOR INSTALLED CI-YWO Variance - Contractor Invoice	Salvage -M02	108040	1
5T721995	RSO, 8/21, ENFIELD, ENFIELD STREET,	RSO, 8/21, ENFIELD, ENFIELD STREET, P 2932 - REPLACED 60' OF 1/0 QUAD AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T820043	COMP 3/2 CCC - ENFIELD THE MEADOWS	COMP 3/2 CCC - ENFIELD THE MEADOWS P#18 - RPL BLK FG POLE & PTT 150HPS AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T820195	CLH - 2018 DEF POLE REPLACEMENT - P	CLH - 2018 DEF POLE REPLACEMENT - P22490 KING SPRING RD, WINDSOR LOCKS AP2-YWO Total Cost Variance Met - Variance :22.1396 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5T820821	Vernon Ave, Vernon- pole # 53 - Inf	Vernon Ave, Vernon- pole # 53 - Infrared Repairs - Minor (IFOH) CL-YWO Variance - Contractor Labor	Salvage -M02	108040	1
5T821166	CDOT134-147 W. Stafford Rd. Rte 190	CDOT134-147 W. Stafford Rd. Rte 190 Stafford Reconductor 336 TW Phase 1 JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
5T821517	Main St, Somers Rejects P-340, 350,	Main St, Somers Rejects P-340, 350, 357 & 358 AP2-YWO Total Cost Variance Met - Variance :6.952 MIN.:-50 MAX.:50	Salvage -M02	108040	1
5T821527	2019 POLE INTEGRITY PROGRAM - SOMER	2019 POLE INTEGRITY PROGRAM - SOMERS, WATCHAUG RD P-8589S AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T822185	8 Belle Ave.Enfield Replace service	8 Belle Ave.Enfield Replace service from P- 14154 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5T822402	CDOT 134-147 Orcuttville Rd. Rt 319	CDOT 134-147 Orcuttville Rd. Rt 319 Stafford Phase 2 pole relocations JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
5T920058	CDOT 129-115 Turnpike Rd. Somers Br	CDOT 129-115 Turnpike Rd. Somers Bridge replacement project JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
5T920988	CDOT 129-115 Turnpike Rd. Somers. M	CDOT 129-115 Turnpike Rd. Somers. Move 1PH primary to permanent location JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
5T922225	294 Hartford Ave E.Granby Remove se	294 Hartford Ave E.Granby Remove service to house/install on new garage P-576 AP1-YWO Total Cost Less Than 7K	Salvage -M02	108040	1
5W220907	RA CDOT 32-130 Main St., Coventry	RA CDOT 32-130 Main St., Coventry - STA 16+00 to 19+00 (pole 32 to pole 30) JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
5W220938	RA CDOT 32-130 Main St., Coventry	RA CDOT 32-130 Main St., Coventry - STA 16+00 to 22+50 (pole 32 to pole 27) JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
5W420455	JV Crystal Ln Mansfield replace 3 w	JV Crystal Ln Mansfield replace 3 wood SL poles rotted. UG complex AP2-YWO Total Cost Variance Met - Variance :17.4631 MIN.:-50 MAX.:50	Salvage -M02	108040	1

work_order_number	description	long_description	cost_element_group	ferc_account	percent
5W613498	RA CDOT 32-130 Main St. Coventry -	RA CDOT 32-130 Main St. Coventry - STA 24+00 to 31+50 (pole 25 to 20) JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
5W720003	RA CDOT 32-130 Main St. Coventry -	RA CDOT 32-130 Main St. Coventry - STA 23+00 to 24+00 (pole 26) JE-YWO Variance Job Type Exclusion	Salvage -M02	108040	1
80072021	COMP NTW 11/11/24* ESSEX, 5 LITTLE		Salvage -M02	108040	1
80238606	* MAP COMP ASP JTR, CD01701-02, Blm		Salvage -M02	108040	1
80399654	Riverside 2R RBI Rls	Riverside 2R Replace Battery Install Release, scope also includes replacing the battery charger<!-- RICH TEXT -->	Salvage -M02	108040	1
CS000231	Goodwin Lane 22 - Remove Substation	Remove and scrap all steel structures and electrical equipment in the substation including the transformers. All foundations will be cut below grade, trap rock and fence will be removed. Environmental remediation of the site soil will be covered under this project if necessary.	Salvage -M02	108040	1
STORE011	Stores clearing	STORE011OPSNTRELEXPENSES11	Salvage -M02	163010	1
VH1DRT24	CT 11 2024 Sale of Vehicles	CT 11 2024 Sale of Vehicles	Salvage -M02	108040	1
VH1DRT25	CT 11 2025 Sale of Vehicles	CT 11 2025 Sale of Vehicles	Salvage -M02	108040	1