Date Filed: October 06, 2026

Witness: John P. DiPaola-Tromba, Sean D. Redding and Jenna Turner
Request from: Office of Consumer Counsel

Question:

(MS24E) Please refer to Exhibit ACCT-2(CLP-5A-06)(MS24E), p. 1-6. Did these crews perform work at any site or were they on standby at the Cheshire Work Center on March 11 and March 12? If they performed work, please indicate where they worked and how the Company knows about and validated that work.

Response:

The individual referred to in Exhibit ACCT-2(CLP-5A-06)(MS24E), pages 1-3, is providing contractor tree crew supervision and dispatching to support storm restoration. The contractor's supervisory personnel do not maintain records of specific crew dispatch locations during storm events because they are not personally responding to each work site. Their role is to supervise operations and dispatch the tree crews performing the work to locations identified through the Company's restoration process.

The tree crew referred to in Exhibit ACCT-2(CLP-5A-06)(MS24E), pages 4-6, worked two 16-hour shifts on March 11, 2024, and March 12, 2024, which was billed as work time. There is no standby designation or rate for tree crews. The crew did not record any ticket locations.