Date Filed: October 06, 2026

Witness: John P. DiPaola-Tromba, Sean D. Redding and Jenna Turner
Request from: Office of Consumer Counsel

Question:

(MS24E) Please refer to Exhibit ACCT-2(CLP-5A-05)(MS24E), p. 34-36. Did this crew perform work at any site or were they on standby at the Newtown Work Center on March 11 and 12? If they performed work, please indicate where they worked and how the Company knows about and validated that work.

Response:

This individual referred to in Exhibit ACCT-2(CLP-5A-05)(MS24E), pages 34-36, is providing contractor tree crew supervision and dispatching to support storm restoration. The contractor's supervisory personnel do not maintain records of specific crew dispatch locations during storm events because they are not personally responding to each work site. Their role is to supervise operations and dispatch the tree crews performing the work to locations identified through the Company's restoration process.